

PEARL RIVER PUBLIC SCHOOL DISTRICT

BID NUMBER RFB-PR-2019-13

BURGLAR/FIRE ALARM & PA/CLOCK SYSTEM

OPENING: AUGUST 27, 2018 AT 11:00 A.M.

Vendor: _____

PEARL RIVER SCHOOL DISTRICT
135 WEST CROOKED HILL ROAD
PEARL RIVER, NEW YORK 10965

845-620-3911 Business Office

NOTICE TO BIDDERS

In accordance with the provisions of Section 103 of the General Municipal Law, an advertisement for bids was published in The Journal News on August 21, 2018. As stated in such notice, bids will be publicly opened and read in the Administrative Office, 135 West Crooked Hill Road, Pearl River, NY on August 27, 2018 at 11:00 a.m. We would appreciate your submitting a bid.

Please contact us if you have any questions.

This bid contains the following items.

1. General Conditions
2. Bid Instructions
3. Specifications
4. Bid Proposal and Required Bid Form (if necessary)
5. Bid Proposal Certifications
6. Prior year Fire Alarm Inspection reports

Kathleen Ryan
Purchasing Agent

PEARL RIVER UNION FREE SCHOOL DISTRICT
ADMINISTRATIVE OFFICES
135 WEST CROOKED HILL ROAD
Pearl River, N.Y. 10965

845-620-3911 BUSINESS OFFICE

Town of Orangetown
County of Rockland

GENERAL CONDITIONS

(For the purchase of materials, supplies, services, and equipment)

All invitations to bid issued by the above named School District will bind bidders and successful bidders to the conditions and requirements set forth in these general conditions, and such conditions shall form an integral part of each purchase contract awarded by the School District.

DEFINITIONS

"School District"	- shall be the legal designation of the district.
"Board"	- the Board of Education of the school district.
"Bid"	- an offer to furnish materials, supplies, services, and or equipment in accordance with the invitation to bid, the general conditions, and the specifications.
"Bid Offer"	- the form on which the bidder submits his bid.
"Bidder"	- any individual, company, or corporation submitting a bid.
"Successful bidder"	- any bidder to whom an award is made by the school district.
"Specification"	- description of materials, supplies, services, and/or equipment and the conditions for its purpose.

BIDS

1. The date and time of bid opening will be given in the Notice to Bidders.

2. All bids must be submitted on and in accordance with forms provided by the board.

3. All bids received after the time stated in the Notice to Bidders may not be considered and will be returned to the bidder. The bidder assumes the risk of any delay in the mail or in the handing of the mail by employees of the school district. Whether sent by mail or by means of personal delivery, the bidder assumes responsibility for having his bid deposited on time at the place specified. The District will not accept facsimile or e-mail bids.

4. All information required by Notice to Bidders, Specifications, and Bid Offer, in connection with each item against which a bid is submitted, must be given to constitute a regular bid.

5. The submission of a bid will be construed to mean that the bidder is fully informed as to the extent and character of the supplies, materials, services or equipment required and a representation that the bidder can furnish the supplies, services, materials, or equipment satisfactorily in complete compliance with the specifications.

6. No alteration, erasure, or addition is to be made in the typewritten or printed matter. Deviations from the specifications must be set forth in space provided in bid for this purpose.

7. Prices and information required, except signature of bidder, should be typewritten for legibility. Illegible or vague bids may be rejected. All signatures must be original signatures. Facsimile, printed, or typewritten signatures are not acceptable.

8. Sales to school districts are not affected by any fair trade agreements. (General Business Law, ch. 39, Sec. 369-a, Sub. 3, L 1941)

9. No charge will be allowed for federal, state, or municipal sales and excise taxes since the school district is exempt from such taxes. The price bid shall be net and shall not include the amount of any such tax. Exemption certificates, if required, will be furnished on forms provided by the bidder.

10. In all specifications, the words "or equal" are understood after each article giving manufacturer's name or catalog reference, or on any patented article. The decision of the school district as to whether an alternate or substitution is in fact "equal" shall be final. If bidding on items other than those specified, bidder must in every instance give the trade designation of the article, manufacturers name, and detailed specification of item he proposes to furnish. Otherwise, bid will be construed as submitted on the identical item as specified

11. Bids on equipment must be standard new equipment, of latest model, and in current production, unless

otherwise specified.

12. All regularly manufactured stock electrical items must bear the label of the Underwriters' Laboratories, Inc.

13. When bids are requested on a lump sum basis, bidder must bid on each item in the lump sum group. A bidder desiring to bid "no charge" on an item in a group must so indicate; otherwise bid for the group may be rejected.

14. All prices quoted must be "per unit" as specified; eg, do not quote "per case" when "per dozen" is requested; otherwise, bid may be rejected.

15. Bidder must insert the price per unit and the extensions against each item in his bid. In the event of a discrepancy between the unit price and the extension, the unit price will govern. Prices shall be extended in decimals, not fractions.

16. Prices shall be net, including transportation and delivery charges fully prepaid by the successful bidder to destination indicated in the proposal. If award is made on any other basis, transportation charges must be prepaid by the successful bidder and added to the invoice as a separate item. In any case, title shall not pass until items have been delivered and accepted.

17. The bidder must submit the Bid Proposal Certification and the Certificate and Signature Form (Appendixes A & B) pursuant to sec. 103-d of the New York State General Municipal Law.

18. All bids must be sealed. They may be submitted either in plain or opaque envelopes, or in those furnished by the school district. All bids must be addressed to the Purchasing Agent. Bid envelopes must be clearly marked 'Bid'. Also the date and time of the bid opening, as indicated on the Notice to Bidders, must appear on due envelope. Bids must not be attached to or enclosed in packages containing bid samples. Telephoned quotations or amendments will not be accepted at any time. The District will not accept facsimile or e-mail bids.

19. No interpretation of the meaning of the specifications or other contract document will be made to any bidder orally. Every request for such interpretation should be in writing, addressed to the school district, not later than five (5) days prior to the date fixed for the opening of bids. Notice of any and all such interpretations and any supplemental instructions will be sent to all bidders of record by the school district in the form of addenda to the specifications. All addenda so issued shall become a part of the contract documents.

20. If the supplies, materials, services or equipment are to be delivered over an extended period of time, or if the specifications so state, then the successful bidder may be required to execute an agreement in relation to the performance of his contract, such agreement to be executed by the bidder within 15 days after notification to execute such contract. If the specifications so state, the successful bidder also may be required to furnish a performance bond equal to the full amount of the contract to guarantee the faithful performance of such contract. Such performance bond shall be maintained in full force and effect until the contract shall have been fully performed. The surety company furnishing such performance bond shall be authorized to do business in the State of New York and must be satisfactory to the attorney for the school district. The performance bond shall be executed by the successful bidder at the time of the execution of the contract by the successful bidder and the board. The school district reserves the right to specify

that a bid bond is required and/or that a cash deposit in lieu of a performance bond shall be deemed sufficient to secure performance for no additional expense.

SAMPLES

21. All specifications are minimum standards; and accepted bid samples do not supersede specification for quality unless bid sample is superior, in which case deliveries must be the same identity and quality as accepted bid sample.

22. The school district reserves the right to request a representative sample of the item quoted upon either prior to the award or before shipments are made. If the sample is not in accordance with the requirements of the specification, the school district may reject the bid; or, if award has been made, cancel the contract at the expense of the successful bidder.

23. Samples, when required, must be submitted strictly in accordance with instructions; otherwise, bid may not be considered. If samples are requested subsequent to bid opening, they shall be delivered within ten (10) days of the request, or as directed, for bid to have consideration. Samples must be furnished free of charge and must be accompanied by descriptive memorandum invoices indicating if the bidder desires their return and specifying the address to which they are to be returned provided they have not been used or made useless by tests. Award samples may be held for comparison with deliveries. The school district will not be responsible for any samples destroyed or mutilated by examination or testing. Samples shall be removed by the bidder at his expense. Samples not removed within fifteen (15) days after written notice to the bidder will be regarded as abandoned and the school district shall have the right to dispose of them as its own property.

24. When a specification indicates that an item to be purchased is to be equal to a sample, such sample will be on display at a designated location in the school district. Failure on the part of the bidder to examine sample shall not entitle him to any relief from the conditions imposed in the proposal, specification, etc.

AWARD

25. Awards will be made to the lowest responsible bidder, as will best promote the public interest, taking into consideration the reliability of the bidder, the quality of the materials, services, equipment, or supplies to be furnished, their conformity with the specifications, the purposes for which required, and the terms of delivery.

26. The school district reserves the right to reject all bids. Also reserved is the right to reject, for cause, any bid in whole or in part; to waive technical defects; qualifications; irregularities; and omissions if in its judgment the best interests of the district will be served. Also reserved is the right to reject bids and to purchase items on State or County contract or BOCES or other municipal bids if such items can be obtained on the same terms, conditions, specifications, and at a lower price.

27. The school district reserves the right to make awards within forty-five (45) days after the date of the bid opening during which period bids may not be withdrawn unless the bidder distinctly states in his bid that acceptance thereof must be made within a shorter specified time.

28. Where a bidder is requested to submit a bid on individual items and also on a total sum or sums, the right

is reserved to award bids on individual items or on total sums.

BID MISTAKE

29. The withdrawal of a bid based upon a unilateral mistake shall be allowed only in strict compliance with the requirements of Sec. 103 (11) of the New York State General Municipal Law.

CONTRACT

30. Each bid will be received with the understanding that the acceptance thereof in writing by the school district, approved by the board of education, to furnish any or all of the items described therein shall constitute a contract between the successful bidder and the school district. Contract shall bind the successful bidder on his part to furnish and deliver at the prices and in accordance with the conditions of his bid. Contract shall bind the school district on its part to order from such successful bidder (except in the case of emergency) and to pay for at the contract prices, all items ordered and delivered, unless otherwise specified.

31. The placing in the mail of a notice of award or purchase order to a successful bidder, to the address given in his bid, will be considered sufficient notice of acceptance of contract.

32. If the successful bidder fails to deliver within the time specified or within reasonable time as interpreted by the school district, or fails to make replacement of rejected articles, when so requested, immediately or as directed by the school district, the school district may purchase from other sources to take the place of the item rejected or not delivered. The school district reserves the right to authorize immediate purchase from other sources against rejections on any contract when necessary. On all such purchases the successful bidder agrees to reimburse the school district promptly for excess costs occasioned by such purchases. Should the cost be less, the successful bidder shall have no claim to the difference. Such purchases will be deducted from contract quantity. Whenever the school district seeks legal enforcement of the provisions of said contract, the bidder shall be liable for payment of the school district's legal costs, including reasonable attorney's fees.

33. A contract may be canceled at the successful bidder's expense upon non-performance of contract.

34. If the successful bidder fails to deliver as ordered, the school district reserves the right to cancel the contract and purchase the balance from other sources at the successful bidder's expense.

35. Cancellation of contract for any reason may result in removal of the successful bidder's name from mailing list for future proposals for an indeterminate period.

36. When materials, equipment, services or supplies are rejected, they must be removed by the successful bidder from the premises of the school district within five (5) days of notification. Rejected items left longer than five (5) days will be regarded as abandoned, and the school district shall have the right to dispose of them as its own property.

37. No items are to be shipped or delivered until receipt of an official order from the school district.

38. It is mutually understood and agreed that the successful bidder shall not assign, transfer, convey,

sublet, or otherwise dispose of the contract or his right, title, or interest therein, or his power to execute such contract to any other person, company, or corporation, without the previous written consent of the school district.

INSTALLATION OF EQUIPMENT

39. The successful bidder shall clean up and remove all debris and rubbish resulting from his work from time to time as required or directed. Upon completion of the work the premises shall be left in a neat, unobstructed condition, and the buildings broom cleaned, and everything in perfect repair and order. Old materials are the property of the successful bidder unless otherwise specified.

40. Equipment, supplies, services and materials shall be stored at the site only on the approval of the school district and at the successful bidder's risk. In general, such on-site storage should be avoided to prevent possible damage or loss of the material.

41. Work shall be progressed so as to cause the least inconvenience to the school district and with proper consideration for the rights of other successful bidders or workmen. The successful bidder shall keep in touch with the entire operation and install his work promptly.

42. Bidders shall acquaint themselves with conditions to be found at the site and shall assume all responsibility for placing and installing the equipment in the locations required.

43. Equipment for trade-in shall be dismantled by the successful bidder and removed at his expense. The condition of the trade-in equipment at the time it is turned over to the successful bidder shall be the same as covered in the specifications, except as affected by normal wear and tear from use up to the time of trade-in. All equipment is represented simply as is. Equipment is available for inspection only at the delivery point listed for new equipment unless otherwise specified.

44. The successful bidder guarantees:

- (a) His products against defective material or workmanship and or repair or replace any damages or marring occasioned in transit.
- (b) To furnish adequate protection from damage for all work and to repair damages of any kind for which the vendor or its workers are responsible, to the building or equipment, to their own work, or to the work of other successful bidders.
- (c) To carry adequate insurance to protect the school district from loss in case of accident, fire, theft, etc.
- (d) That all deliveries will be equal to the accepted bid sample.
- (e) That the equipment or furniture offered is standard, new, latest model of regular stock product or as required by the specifications, with parts regularly used for the type of equipment or furniture offered; also that no attachment or part has been substituted or applied contrary to manufacturer's recommendations and standard practice. Every unit delivered must be guaranteed against faulty material and workmanship for a period of at least one year from date of delivery. If during this period such faults develop, the successful bidder agrees to

replace the unit or the part affected without cost to the school district

Any merchandise provided under the contract which is or becomes defective during the guarantee period shall be replaced by the successful bidder free of charge with the specific understanding that all replacements shall carry the same guarantee as the original equipment (one year from the date of acceptance of the replacement). The successful bidder shall make any such replacement immediately upon receiving notice from the school district.

DELIVERY

45. Delivery must be made as ordered and in accordance with the proposal and specification. If delivery instructions do not appear on order, it will be interpreted to mean prompt delivery (not to exceed 30 days). The decision of the school district as to reasonable compliance with delivery terms shall be final. Burden of proof of delay in receipt of order shall rest with the successful bidder. Failure to deliver because of delayed payments or for any other reason except that described in Paragraph 52 will be cause for open market purchase at the expense of the successful bidder.

46. The school district will not schedule any deliveries for Saturdays, Sundays, or legal holidays, except commodities required for daily consumption or where the delivery is an emergency, a replacement, or is overdue, in which event the convenience of the school district shall govern.

47. Items shall be securely and properly packed for shipment, storage, and stocking in new shipping containers and according to accepted commercial practice, without extra charge for packing cases, baling, or sacks.

48. The successful bidder shall be responsible for delivery of items in good condition at point of destination. He shall file with the carrier all claims for breakage, imperfections, and other losses, which will be deducted from invoices. The receiving school district will note for the benefit of successful bidder when packages are not received in good condition.

49. Unless otherwise stated in the specifications, all items must be delivered into and placed at a point within the building as directed by the shipping instructions or the agent for the school district. The successful bidder will be required to furnish proof of delivery in every instance.

50. Unloading and placing of the equipment and furniture is the responsibility of the successful bidder, and the school district accepts no responsibility for unloading and placing of equipment. Any costs incurred due to the failure of the successful bidder to comply with this requirement will be charged to him. No help for unloading will be provided by the school district, and suppliers should notify their truckers accordingly.

51. All deliveries shall be accompanied by delivery tickets or packing slips. Ticket shall contain the following information for each item delivered:

Contract Number

Purchase Order Number

Name of Article

Item Number

Quantity

Name of the successful bidder

Carton shall be labeled with purchase order number, successful bidder's name and general statement of contents. Failure to comply with this condition shall be considered sufficient reason for refusal to accept the goods.

PAYMENTS

52. Payment for the used portion of an inferior delivery will be made by the school district on an adjusted price basis.

53. Payment will be made only after correct presentation of claim forms obtained from the ordering school district.

54. Payments of any claim shall not preclude the school district from making claim for adjustment on any item found not to have been in accordance with general conditions and specifications.

SAVE HARMLESS

55. Proposer shall protect, indemnify, defend and save the district harmless from and against any damage, cost or liability, including reasonable attorney's fees, for any or all injuries to persons or property arising from acts or omissions of your company, its officers, employees and agents, including but not limited to claims brought by third parties, employees of the District or employees of the company.

SAVING CLAUSE

56. The successful bidder shall not be held responsible for any losses resulting if the fulfillment of the terms of the contract shall be delayed or prevented by wars, acts of public enemies, fires, floods, acts of God, or for any other acts not within the control of the successful bidder and which by the exercise of reasonable diligence he is unable to prevent.

NONDISCRIMINATION CLAUSE

57. The bidder agrees that it will not discriminate against any employee, applicant for employment or student because of race, creed, color, national origin, religion, sex, age, disability, marital status, sexual orientation or other non-merit factors. Such action shall be taken with reference to, but not be limited to employment practices and provision of services under any contract with the District.

RETURN TO:
BUSINESS OFFICE

BID PROPOSAL

PEARL RIVER SCHOOL DISTRICT
135 WEST CROOKED HILL ROAD
PEARL RIVER, NEW YORK 10965
845-620-3911

BID OPENING: AUGUST 27, 2018

AT 11:00 A.M.

BID NO. RFB-PR-2018-13 BURGLAR/FIRE ALARM & PA/CLOCK SYSTEM

Name of Bidder: _____

Signature of person submitting bid: _____

Printed or typed name of person submitting bid: _____

Title of person submitting bid: _____

Address of bidder: _____

Telephone Number of Bidder (include area code): _____

Date: _____

PEARL RIVER SCHOOL DISTRICT

SPECIAL CONDITIONS DOCUMENT

BID NUMBER: RFB-PR-2018-13

BID TITLE: BURGLAR/FIRE ALARM & PA/CLOCK SYSTEM

1. FOR THE ABOVE REFERENCED BID, A BID BOND –

 IS REQUIRED IN THE AMOUNT OF PERCENT OF TOTAL BID.

 X IS NOT REQUIRED

2. FOR THE ABOVE REFERENCED BID, A PERFORMANCE BOND –

 IS REQUIRED IN THE AMOUNT OF PERCENT OF TOTAL BID.

 X IS NOT REQUIRED

3. FOR THE ABOVE REFERENCED BID, A CASH DEPOSIT IN THE AMOUNT OF 0 % OF THE TOTAL CONTRACT SUM WILL BE REQUIRED WITH FIVE (5) BUSINESS DAYS OF NOTICE OF AWARD, IN LIEU OF A PERFORMANCE BOND.

PEARL RIVER SCHOOL DISTRICT
135 WEST CROOKED HILL ROAD
PEARL RIVER, NY 10965

BID PROPOSAL CERTIFICATION

Firm Name _____

Business Address _____

Telephone Number _____ Date of Bid _____

I. General Bid Certification

The bidder certifies that he will furnish, at the prices herein quoted, the materials, equipment and/or services as proposed on this bid.

II. Non-Collusive Bidding Certification

By submission of this bid proposal, the bidder certifies that he is complying with Section 103-d of the General Municipal Law as follows:

Statement of non-collusion in bids and proposals to political subdivision of the state. Every bid or proposal hereafter made to a political subdivision of the state or any public department, agency or official thereof where competitive bidding is required by statute, rule, regulation, or local law, for work or services performed or to be performed or goods sold or to be sold, shall contain the following statement subscribed by the bidder and affirmed by such bidder as true under the penalties of perjury: Non-collusive bidding specification.

"(A) By submission of this bid, each bidder and each person signing on behalf of any bidder certifies, and in the case of joint bid each party thereto certifies as to its own organization, under penalty or perjury, that to the best of knowledge and belief:

(1) The prices in this bid have been arrived at independently without collusion, consultation, communication or agreement, for the purpose of restricting competition, as to any matter relating to such prices with any other bidder or with any competitor;

(2) Unless otherwise requested by law, the prices which have been quoted in this bid have not been knowingly disclosed by the bidder and will not knowingly be disclosed by the bidder prior to opening, directly or indirectly, to any other bidder or to any competitor; and

(3) No attempt has been made or will be made by the bidder to induce any other person, partnership or corporation to submit or not to submit a bid for the purpose of restricting competition."

(B) A bid shall not be considered for award nor shall any award be made where (A) (1) (2) and (3) above have not been complied with; provided, however, that if in any case the bidder cannot make the foregoing certification, the bidder shall so state and shall furnish with the bid a signed statement which sets forth in detail the reasons therefore. Where (A) (1) (2) and (3) above have not been completed with, the bid shall not be considered for award nor shall any award be made unless the head of the purchasing unit of the political subdivision, public department, agency or official thereof to which the bid is made, or his designee, determines that such disclosure was not made for the purpose of restricting competition.

(1) The fact that a bidder (2) has (a) published price lists, rates, or tariffs covering items being procured, (b) had informed prospective customers of proposed or pending publication of new or revised price lists for such items, or (c) has sold the same items to other customers at the same prices being bid, does not constitute, without more, a disclosure within the meaning subparagraph one (A).

(2) Any bid hereafter made to any political subdivision of the state or any public department, agency or official thereof by a corporate bidder for work or services performed or to be performed or goods sold or to be sold, where competitive bidding is required by statute, rule, regulation, or local law, and where such bid contains the certification referred to in subdivision one of the section, shall be deemed to have been authorized by the board of directors to the bidder, and such authorization shall be deemed to include the signing and submission of the bid and the inclusion therein of the certificate as to non-collusion as the act and deed of the corporation.

Signature (Authorized) _____

Title _____

APPENDIX A

Pearl River School District
135 West Crooked Hill Road
Pearl River, NY 10965

IRAN DIVESTMENT ACT CERTIFICATION

The Iran Divestment Act of 2012 ("Act"), Chapter 1 of the 2012 Laws of New York, added State Finance Law (SFL), §165-a and General Municipal Law §103-g, effective April 12, 2012. Under the Act, the Commissioner of the New York State Office of General Services ("OGS") developed a list ("Prohibited Entities List") of "persons" who are engaged in "investment activities in Iran" (both are defined terms in the law). In accordance with SFL §165-a(3), the Prohibited Entities List may be found on the OGS website at: <http://www.ogs.ny.gov/about/regs/docs/ListofEntities.pdf>.

Pursuant to General Municipal Law §103-g, by signing below, Bidder certifies as true under the penalties of perjury that: By submission of this proposal each Bidder and each person signing on behalf of any Bidder certifies, and in the case of a joint proposal each party thereto certifies as to its own organization, under penalty of perjury, that to the best of its knowledge and belief that each Bidder is not on the list created pursuant to paragraph (b) of subdivision 3 of section 165-a of the State Finance Law.

A proposal shall not be considered for award nor shall any award be made where the certification has not been made, provided, however, that if in any case the Bidder cannot make the certification, the Bidder shall so state and shall furnish with the proposal a signed statement which sets forth in detail the reasons therefor. The Pearl River School District ("District") may award a contract to a Bidder who cannot make the required certification on a case-by-case basis if:

- 1) The investment activities in Iran were made before April 12, 2012, the investment activities in Iran have not been expanded or renewed after April 12, 2012, and the person has adopted, publicized, and is implementing a formal plan to cease the investment activities in Iran and to refrain from engaging in any new investments in Iran; or
- 2) The District makes a determination that the goods and services are necessary for the District to perform its functions and that, absent such exemption, the political subdivision would be unable to obtain the goods or services for which the contract is offered. Such determination shall be made in writing and shall be a public document.

During the term of the Contract, should the District receive information that a person is in violation of the above-referenced certifications, the District will offer the person an opportunity to respond. If the person fails to demonstrate that it has ceased its engagement in the investment which is in violation of the Act within 90 days after the determination of such violation, then the District shall take such action as may be appropriate including, but not limited to, imposing sanctions, seeking compliance, recovering damages, or declaring the contractor in default.

The District reserves the right to reject any bid, proposal, contract or request for assignment for an entity that appears on the Prohibited Entities List prior to the award or execution of a contract or any renewal thereof, as applicable, and to pursue a responsibility review with respect to any entity that is awarded a contract and appears on the Prohibited Entities List after contract award.

DATE

SIGNATURE

BUSINESS NAME

PRINTED NAME

TITLE

CERTIFICATE AND SIGNATURE FORM

PLEASE COMPLETE AND RETURN WITH YOUR BID:

THE BIDDER DECLARES AND CERTIFIES:

- 1ST: THAT NO MEMBER OF THE BOARD OF EDUCATION OF THE PEARL RIVER SCHOOL DISTRICT, COUNTY OF ROCKLAND NOR ANY OFFICER OR EMPLOYEE OR PERSON WHOSE SALARY IS PAYABLE IN WHOLE OR IN PART FROM THE TREASURY OF SAID BOARD OF EDUCATION IS DIRECTLY OR INDIRECTLY INTERESTED IN THIS BID OR IN THE MATERIALS, EQUIPMENT, OR SERVICES TO WHICH IT RELATES, OR IN ANY PORTION OF THE PROFITS THEREOF.
- 2ND: THAT THE SAID BIDDER HAS CAREFULLY EXAMINED THE INSTRUCTIONS TO BIDDERS, SCHEDULES AND SPECIFICATIONS PREPARED UNDER THE DIRECTION OF THE BOARD OF EDUCATION, AND WILL, IF SUCCESSFUL IN THIS BID, FURNISH AND DELIVER AT THE PRICES BID AND WITHIN THE TIME STATE, ALL THE MATERIALS, EQUIPMENT OR SERVICES FOR WHICH THIS BID IS MADE.

THE FULL NAMES AND TITLES OF ALL PERSONS INTERESTED IN THIS BID AS PRINCIPALS ARE AS FOLLOWS:

DATE: _____

PHONE: _____

FIRM: _____

FAX: _____

ADDRESS: _____

NAME: _____
(CONTACT PERSON FOR BID INQUIRIES)
(IF SAME AS AUTHORIZED, LEAVE BLANK)

AUTHORIZED
SIGNATURE: _____

TITLE: _____

APPENDIX B

PEARL RIVER SCHOOL DISTRICT
PEARL RIVER, NEW YORK

Receipt Confirmation Form

Please complete and return this confirmation form within 5 working days of receiving bid package to:

Purchasing Department
Purchasing Agent
Pearl River School District
135 West Crooked Hill Road
Pearl River, NY 10965

RE: RFB-PR-2018-13 BURGLAR/
FIRE ALARM & PA/CLOCK SYSTEM

Telephone: 845-620-3911

Fax: 845-620-3934

Failure to return this form may result in no further communication or addenda regarding this Bid.

Company Name: _____

Address: _____

City, State, Zip: _____

Contact Person: _____

Phone Number: _____ Ext: _____ Fax: _____

I have received a copy of the above noted bid.

_____ We will be submitting a bid.

_____ We will not be submitting a bid.

If you are responding that you are not submitting a bid, please explain:

If a bidder's meeting has been arranged for this bid, please indicate if you plan to attend:

Yes / No

PEARL RIVER PUBLIC SCHOOL DISTRICT

**INVITATION TO SUBMIT PROPOSALS FOR BURGLAR/FIRE ALARM & PA/CLOCK SYSTEM
INSPECTION, MONITORING & MAINTENANCE**


The Board of Education of the Pearl River Union Free School District will accept sealed proposals burglar alarm, fire alarm system monitoring, maintenance & inspection and public address/clock system maintenance at the Business Office, 135 West Crooked Hill Road, Pearl River, NY 10965, until 11:00 A.M., EST., August 27, 2018.

Conditions and instructions for submitting proposals, as well as the necessary proposal forms, are available at the Business Office, 135 West Crooked Hill Road, Pearl River, NY 10965 (Telephone: 845-620-3911).

The Pearl River Union Free School District reserves the right to accept or reject any or all proposals, to waive any informalities in the proposals received and to accept the proposal deemed most advantageous to the best interest of the school district.

Pearl River Union Free School District

By: _____


Kathleen Ryan
Purchasing Agent

PEARL RIVER PUBLIC SCHOOL DISTRICT

INTRODUCTION

The Pearl River Union Free School District is requesting proposals for burglar alarm, fire alarm system monitoring, maintenance & inspection and public address/clock system maintenance

It is the School District's intention to determine the lowest responsible bidder through evaluation of various criteria including, but not limited to price and overall cost of services to be rendered, strength and reputation, depth of experience, and quality of services.

The Board of Education will appoint a review committee to screen all proposals and recommend finalists to the Board of Education for final selection. All proposals and information submitted for review by the review committee are hereby declared to be part of the contractual proposal for final review by the Board of Education.

The evaluation by the review committee is intended to identify those best able to conduct annual boiler/burner cleaning & maintenance. The results of the evaluation of the proposals submitted by the various companies by individual members of the committee or the committee as a whole shall be accepted without recourse. This will be a subjective evaluation based on the individual committee member's judgment of the proposals as related to the criteria and weighing factors.

The successful vendor will provide necessary leadership, coordination and cooperation to assure the plans and services responsive to needs of the school district and service goals are consistent with state requirements and all applicable laws.

It is understood that the Board of Education reserves the right to reject any or all proposals, or waive any informality in a proposal; and, it is expressly contemplated that no contract exists on the part of the school district until formal written notice has been given or until a contract is executed.

In this instance of request for several proposals, it is understood that the Board of Education reserves the right to award a contract for the proposal in the manner deemed to be in the best interest of the school district.

**From: Office of the Purchasing Agent
of the Pearl River School District
135 West Crooked Hill Road
Pearl River, NY 10965**

Re: Burglar alarm, fire alarm system monitoring, maintenance & inspection and public address/clock system maintenance

Conditions and Instructions for submitting proposals:

1. Sealed proposals will be received up to 11:00 A.M., August 27, 2018 at 135 West Crooked Hill Road, Business Office, Pearl River, NY 10965, at which time they will be publicly opened. Late proposals will not be considered.

2. All envelopes containing proposals are to be clearly marked with the number and title of this bid. The envelope itself is to be addressed as follows:

**Pearl River School District
Attn: Business Office
135 West Crooked Hill Road
Pearl River, NY 10965**

3. Acceptance of Proposals content:

The contents of the proposal of the successful company will become the contractual obligations along with the final contract if contractual action ensues. Failure of the successful company to accept these obligations in an agreement may result in cancellation of the award.

4. Economy of Preparation:

Proposals should be prepared simply and economically, providing a straightforward concise description of your company's capabilities to satisfy the requirement of the request for proposal. Special bindings, colored displays, promotional materials, etc. may be included. Emphasis should be on completeness and clarity of content.

5. Save Harmless:

Proposer shall protect, indemnify, defend and save the district harmless from and against any damage, cost or liability, including reasonable attorney's fees, for any or all injuries to persons or property arising from acts or omissions of your company.

6. Rejecting of Proposals:

The Board of Education reserves the right to reject any and all proposals received as a result of this request, or to negotiate separately with any source in any manner necessary to serve the best interests of the school district.

The Board of Education does not intend to award a contract solely on the basis of any response made to this request or otherwise pay for the information solicited or obtained. Subsequent procurement, if any, will be in accordance with the Board of Education contractual action. Non-compliance of the conditions of the proposal may result in disqualification.

7. Incurring Costs:

The Board of Education is not liable for any cost incurred by your company prior to issuance of the agreement, contract or purchase order.

8. Form of Proposal:

All proposals must include the forms supplied for this purpose.

Oral, telephonic or telegraphic proposals are invalid and will not receive consideration.

The work to be provided shall include the furnishing of all labor, materials, equipment, and services necessary, or incidental to this proposal.

Before submitting a proposal, the contractor shall take into consideration the amount and character of work to be done and the difficulties involved in its proper execution; all costs incidental to the work must be included to cover all contingencies essential to this proposal, notwithstanding that every item or contingency is not specifically mentioned herein.

9. Authority for signing proposals:

Proposals are to be signed by authorized individual. Indicate the name of the individual.

10. Assignment:

No contract or order or interest therein shall be transferred or subcontracted by your company to whom such contract or order is given to any other party.

11. Costs to be included in proposal:

The proposal shall contain all estimated costs for providing the scope of services contained in these specifications.

12. Supplemental Information:

All companies submitting proposals must use the forms provided to present the information requested. Proposals submitted that do not meet this condition will be automatically eliminated from consideration. In addition to the submission of the formal proposal form, your company may submit a separate brochure containing descriptive literature about the firm's organization, staff and experience in performing services.

13. Strength and reputation of your company:

A very high priority will be placed in the selection process on companies who have the strength and reputation whereby their services are readily acceptable by New York State Governmental Offices, Federal Agencies, etc.

General Scope of Work

The contractor shall furnish all supervision, labor, materials, equipment, tools, supplies, incidentals and services of every kind necessary, except as specified below, for burglar alarm, fire alarm system monitoring, maintenance & inspection and public address/clock system maintenance (all collectively hereinafter referred to as the "work"). The contractor shall pay all fees and secure all permits necessary to complete the work, in every respect, in a workmanlike manner.

Delivery of any materials must be made in accordance with the proposal and specifications. The decision of the School District as to reasonable compliance with delivery terms shall be final. The School District will not accept any deliveries on Saturdays, Sundays or legal holidays, except if requested.

Proof of proper licensure and certification pursuant to this contract shall be furnished to the School District.

The work to be provided shall include the furnishing of all other labor, materials, equipment, and services necessary, or incidental to, the work.

No travel time will be paid. No vehicle use will be paid in the normal course of transporting approved materials to the job site.

No smoking, consumption of alcoholic beverages, or use of illegal drugs will be permitted anywhere on school grounds.

The successful bidder shall not have any contact or communication with any student.

Before submitting a proposal, the contractor shall take into consideration the amount and character of work to be done and the difficulties involved in its proper execution; all costs incidental to the work must be included to cover all contingencies essential to the work, notwithstanding that every item or contingency is not specifically mentioned herein.

Successful bidders will be required to provide three recent references for similar work.

Payment will be made only after correct presentation of claim forms and/or invoices with required supporting documentation as may be required and within thirty (30) days of receipt of same. Payments on any claim shall not preclude the School District from making a claim for adjustment on any item found not to have been in accordance with the specifications.

Option To Extend The Term Of The Contract/Termination Of Contract

The Pearl River School District shall have the unilateral option of extending or renewing this contract for two (2) consecutive additional periods of twelve (12) months, each upon the same terms and conditions as are contained in this contract. The District, each year, will consider, upon request, an inflationary increase not to exceed the Consumer Price Index for March from the New York, Northeastern New Jersey area based upon index for all urban consumers (C.P.I.-U). Said options shall be deemed to have been exercised upon formal written notification thirty (30) calendar days prior to the expiration of the contract provided that the Purchasing Agent shall have given preliminary notice of the Pearl River School District's intention to renew at least sixty (60) calendar days before the contract is to expire. (Such a preliminary notice will not be deemed to commit the Pearl River School District to exercise the option). If the Pearl River School District exercises the option of the first additional twelve (12) month period, the contract as renewed shall be deemed to include the option provision for the second additional twelve (12) month period. However, the total duration of this contract, including any option(s) under this clause, shall not exceed thirty-six (36) months. This agreement may be terminated upon 30 days notice by the Board of Education or by the contractor subject solely to payment of fees and disbursements as of the date of termination.

Assignability of Contract

The contractor will furnish all labor, materials, equipment and supervision necessary to perform such services. This contractor is prohibited from assigning, transferring, conveying, sub-letting or disposing of this contract or any part thereof, or any payment to become due thereunder, or of his/her right, title or interest therein, or his/her power of execute such contract to any other person or corporation without the previous consent in writing of the Board awarding the contract. In any instance where the contractor fails to comply with this clause, this contract may be immediately declared by the District to be breached.

The Pearl River School District may request and Contractor may perform extra services at such prices and at such times as the parties agree upon in writing.

Termination of Contract

Either party may terminate this agreement for convenience (that is, without cause and for any reason or no reason) upon thirty (30) days prior written notice.

Insurance Requirements

The contractor shall carry public liability insurance in an amount not less than \$1,000,000 for injuries, including accidental death, to any one person and subject to the same limits for each person in an amount not less than \$1,000,000 on account of one accident, and contractor's property damage insurance in an amount not less than \$1,000,000. The contractor shall carry automobile liability and automobile property damage insurance in the same limits as stipulated above.

Prior to commencing work, the successful bidder shall provide a Certificate of Insurance with the required limits stating that the "Pearl River School District and its Board of Education, employees, authorized volunteers and committee members and student teachers are named as additional insured" with all rights and privileges of the policy contract without the responsibility to pay premiums prior to the signing of the contract.

Contractor must provide proof of Worker's Compensation coverage for its employees.

The terms of the insurance coverage must also include a minimum of thirty (30) days prior written notification to the District in the event that the insurance is to be cancelled.

Bid Bond

A bid bond is not required for this contract.

Proposal

The district shall have the right to reject any or all proposals, to waive any informalities, or to accept the proposals deemed best for the Pearl River Union Free School District.

The proposal will be firm and may not be withdrawn for a period of sixty (60) days after the scheduled closing time for receiving proposals.

It is to be understood that representatives of the Pearl River School District shall have the right to contact owners for which you were engaged for one or more projects to obtain information about the type and quality of services performed in order to evaluate and select a company to be utilized by our school district.

It is also understood and agreed as part of the contract cost that I (we) will complete and prepare all the necessary reports and documents.

Dated at _____ this _____ day of _____, 2018.

Respectfully submitted,

By _____

Firm

Business Address

City State Zip

Signature

Title

PEARL RIVER UNION FREE SCHOOL DISTRICT

**BURGLAR/FIRE ALARM & PA/CLOCK SYSTEM
INSPECTION, MONITORING & MAINTENANCE**

BID PERIOD: SEPTEMBER 1, 2018 THROUGH AUGUST 31, 2019

VENDOR NAME: _____

INTRODUCTION: The Pearl River Union Free School District is seeking to obtain prices from qualified contractors to conduct the maintenance of the public address/clock systems located in its school buildings and the monitoring, maintenance and inspection of fire alarm equipment located in the District's property. The awarded contract will be from September 1, 2018 – August 31, 2019.

BID PORTIONS: Vendors should be aware that there are three portions to this bid, one each for burglar alarm systems, fire alarm systems and the public address systems. The bid may be awarded to one vendor or more vendors as benefits the district.

QUALIFICATIONS: Each proposal must be accompanied by a verified statement of the bidder showing the following:

- a. A list of buildings of other Public Schools where the Bidder has performed similar services. The bidder shall have performed such services within a period of not less than three (3) years.
- b. The name of a bank reference to the financial stability of the Bidder.
- c. The Bidder shall be prepared to submit proof of financial responsibility as required by the school district.
- d. Balance sheets as of December 31, 2017.

GENERAL TERMS: The listings of locations provided within is subject to change, if at any time a location is closed, opened, or relocated, they shall be part of this contract.

Preventative maintenance is expected to be billed at a fixed rate per location. Any service required above and beyond normal manufacturer preventative maintenance will require an estimate to be approved by the Facilities Director before any work is performed. Any work performed above preventative maintenance must be billed on a separate invoice at the rates agreed upon herein.

Service shall encompass all facilities and equipment necessary to implement the desired operations. The Contractor shall be required to coordinate all activities with prior contractors in order to maintain a smooth transition of service.

The Contractor shall provide preventative maintenance to include all parts and labor on all system components. The Contractor is required to repair or replace any defective components to maintain the systems in proper operating condition. Requests for repair or

replacement shall be approved in advance by the Facilities Director prior to any actual work being performed by the Contractor.

The Contractor shall be responsible to provide a proposed schedule for annual testing to the District a minimum of two weeks (10 working days) before the actual inspections occur.

SPECIFICATIONS – BURGLAR ALARM SYSTEMS: Furnish all labor and material necessary to perform monitoring, maintenance and inspection of the District's burglar alarm equipment. In the event of a malfunction, the vendor shall respond within two (2) hours. The Contractor shall make service available twenty (24) hours per day, seven (7) days per week.

The Contractor shall ensure that District selected individuals have the ability to make updates to security panels at all facilities. The Contractor shall also give a representative of the District the ability to make updates to all the locations involved at no extra charge.

The Contractor shall be available during normal business hours for service issues to include, but is not limited to: adding or modifying users, such as changing employee assignment or supervisor locations and troubleshooting problems such as why an alarm will not arm or disarm.

Contract shall perform all their own maintenance. Sub Contractor's will only be allowed upon receiving written approval in advance from the Facilities Director.

The Contractor shall, in performing the services as described herein, utilize technicians skilled in the service of the described systems. The Contractor shall have in his/her employment a sufficient number of trained technicians so that all service calls are answered promptly. The Contractor shall respond to the District by telephone to all service calls within five minutes of report of occurrence. The Vendor shall physically respond to the site within two (2) hours after report of occurrence.

The District may request the Contractor to provide security clearance and/or background checks for any and all Contractor representatives that may work in any facility.

The Contractor shall maintain or have readily available spare parts and properly trained personnel to support the equipment throughout the duration of the contract. The Contractor shall provide only replacement parts that are new and of the same quality and brand name as that being replaced. Substitutions will be permitted only with prior authorization of the Facilities Director or his designated representative. The contractor must get a service ticket signed by the head custodian and leave a copy in order to get paid.

All work must be performed in such a manner as not to inconvenience building occupants. The Contractor shall determine the Districts normal working conditions and activities in progress and shall conduct the work in the least disruptive manner.

The District shall be responsible to provide reasonable means of access to all equipment covered by the agreement and promptly notify the Contractor of any malfunction in the system(s) which comes to the District's attention.

The Contractor shall secure and pay for all permits, inspections and licenses necessary for the execution of the work.

The monitoring services to be performed shall consist of the following:

The category of Monitoring services is for the purpose of Intrusion Alarms. Monitoring service shall include twenty-four hour dialer signals to each location.

Twenty-four hour monitoring and dispatching services from a U.L. approved central station. The central station must have been in business for a minimum of five (5) years and must have passed a minimum of two consecutive U.L. inspections. Said central station must be staffed by a minimum of two properly trained employees, 24 hours per day, 365 days per year. Said central station must be capable of providing radio cellular backup.

The central station monitoring services shall comply with all current local and national codes including but not limited to NFPA 71, commonly referred to as the "central station standard", NFPA 72 and as detailed in the Fire Alarm Signaling Systems Handbook published by the National Fire Protection Association, Quincy MA 1987.

The central station must be capable of calling several District contact personnel when alarms occur. Failure to comply with this requirement will be grounds for default.

The central station shall compile and retain an accurate list of call back employees for each location.

The approved central station must be able to supervise opening and closing signals of burglar alarms. Provide opening and closing tracking reports electronically every week, which shall include: the date and time, the location, was it opened/closed, by whom and any activity. Also, provide daily reports of any alarm signal consisting of the time of alarm, name of the person notified and the cause of the alarm if known. Other reports may be added as the need arises.

The central station shall provide monthly trouble reports summarizing activities for the previous month reports. The Contractor must meet with the District either in person or via telephone conference call regarding corrective actions and trouble resolution upon request.

The Contractor shall be responsible to coordinate with the existing monitoring service providers to provide seamless transition. The District shall be responsible to provide lockout codes for system dialers or new alarm panels as required. Contractors shall not be allowed to program new dialers with lockout codes without the prior approval of the District.

The Contractor shall be responsible to program the communications equipment to ensure that the various digital signals are communicated and received properly at the central station.

The burglar alarm access system maintenance services to be performed shall consist of the following:

Twenty-four hour service, parts, and labor on all system components; Annual inspection and testing consisting of cleaning and adjusting of all system components, 100% sensor activation and communication central station verification. Said tests to be conducted on weekdays between 8:00 A.M. and 5:00 P.M. All devices shall be tested a minimum of once during a calendar year. The contractor is required to repair or replace any defective components to maintain the systems in proper operating condition. System components shall include any and all back up batteries. Defective peripheral units such as motion detectors and monitoring panels shall be repaired and or replaced. Requests to repair or replace said peripheral units shall be approved in advance by the Facilities Director prior to any actual work being performed by the Contractor.

GENERAL EQUIPMENT LIST

Following is a list of the equipment installed:

Description

Digital controller panel

PIR motion dual event

User specific keypad alphanumeric

Self-testing 2-way radio backup

Self-testing cellular backup

The existing motion detection monitoring devices are listed below by location

All existing Equipment is Honeywell	
Control Panel*	Honeywell 6160
Motion Detectors*	Honeywell IS 2500SN
Evans Park	7 Motion Detectors and one Control Panel
Franklin Ave.	11 Motion Detectors and one Control Panel
Lincoln Avenue	13 Motion Detectors and one Control Panel
135 West Crooked Hill Road (Admin Building)	4 Motion Detectors and two Control Panels

Middle School	27 Motion Detectors and one Control Panel
High School	24 Motion Detectors and one Control Panel
Nauraushsaun Building	4 Motion Detectors and two Control Panels

*Common to all locations

SPECIFICATIONS – FIRE ALARM SYSTEMS: Furnish all labor and material necessary to perform monitoring, maintenance and inspection of the District’s fire alarm equipment. In the event of a malfunction, the vendor shall respond within two (2) hours.

Conduct yearly Fire Alarm equipment inspection and furnish all labor and material necessary to perform monitoring and maintenance of the equipment. The commencement date for inspection must be September 1, 2018 and shall be concluded no later than August 31, 2019. The vendor shall provide twenty-four hour emergency services. In the event of a malfunction, the vendor shall respond within two (2) hours and have the system functional within forty-eight (48) hours. The vendor must have direct access to newly manufactured replacement parts and be able to install, program, and warranty said parts for a minimum of 90 days.

Monitoring Specifications: Monitoring services is for the purpose of monitoring the Early Warning Fire Detection Systems. Monitoring service shall include twenty-four hour dialer signals to each location.

Twenty-four hour monitoring and dispatching services from a U.L. approved central station. The central station must have been in business for a minimum of five (5) years and must have passed a minimum of two consecutive U.L. inspections. Said central station must be staffed by a minimum of two properly trained employees, 24 hours per day, 365 days per year. Said central station must be capable of providing radio cellular backup.

The central station monitoring services shall comply with all current local and national codes including but not limited to NFPA 71, commonly referred to as the “central station standard”, NFPA 72 and as detailed in the Fire Alarm Signaling Systems Handbook published by the National Fire Protection Association, Quincy MA 1987.

The central station must be capable of calling several District contact personnel when alarms occur. Failure to comply with this requirement will be grounds for default.

The central station shall compile and retain an accurate list of call back employees for each location.

The Contractor shall be responsible to coordinate with the existing monitoring service providers to provide seamless transition. The District shall be responsible to provide lockout codes for system dialers or new alarm panels as required. Contractors shall not be allowed to program new dialers with lockout codes without the prior approval of the District.

The Contractor shall be responsible to program the communications equipment to ensure that the various digital signals are communicated and received properly at the central station.

Repair Specifications: The contractor shall furnish all labor, personnel, materials and services required to perform the necessary maintenance and repairs to the fire alarm equipment located in the District's properties.

EMERGENCY SERVICE CALLS:

1. The contractor must respond within two (2) hours of the call.
2. The contractor must be available twenty-four (24) hours a day, seven (7) days a week.
3. The contractor must get a service ticket signed by the head custodian and leave a copy in order to get paid.

Fire Alarm System equipment is located in eight district properties. They are listed below:

- | | |
|---|--|
| 1. Evans Park Elementary School
40 Marion Place
Pearl River, NY 10965 | 2. Franklin Avenue Elementary School
48 Franklin Avenue
Pearl River, NY 10965 |
| 3. Lincoln Avenue Elementary School
115 Lincoln Avenue
Pearl River, NY 10965 | 4. Pearl River Middle School
520 Gilbert Avenue
Pearl River, NY 10965 |
| 5. Pearl River High School
275 East Central Avenue
Pearl River, NY 10965 | 6. Pearl River School District Administration
135 West Crooked Hill Road
Pearl River, NY 10965 |
| 7. A Starting Place (PRSD Property)
664 Orangeburg Road
Pearl River, NY 10965 | 8. Rockland ARC (PRSD Property)
37 Franklin Avenue
Pearl River, NY 10965 |

Inspection Specifications: The contractor shall furnish all labor, personnel, materials and services required to perform the inspection of the fire alarm equipment located in the District's School properties. If during the scheduled inspection of each equipment, the technician should encounter repairs, replacement items, calibrations, adjustments, equipment and labor that are estimated; the contractor shall first submit in writing a complete cost breakdown for labor, materials and equipment to the Buildings and Grounds Department and must receive written authorization before the commencement of any work.

Documentation for inspections shall include exact locations of all individual devices with test results, all applicable control panel voltages, test results of all applicable auxiliary functions, names of technicians performing the service, and all required repairs with cost estimates.

The specifications for the annual inspection shall include the following but not limited to:

- Inspect the entire fire alarm system and components to determine if it is in service in accordance with NFPA 72, State code, and manufacturer's specifications.
- Inspect the general condition of the fire alarm panel and related equipment.
- Inspect and test all smoke and heat detectors in accordance with the manufacturer's specifications and NFPA 72.
- Inspect all fire alarm control panels and remote fire alarm panels.
- Inspect and test all Annunciators and zones, both visually and by tripping a detector.
- Inspect and meter check all batteries.
- Inspect and exercise all flow switches, tamper switches, and low pressure alarms.
- Inspect all output relays and test their activation.
- Inspect smoke detectors for cleanliness and advise owner.
- Test non-restorable heat detector circuits by simulating electrical operation at the wiring connection.
- Function test all accessible heat actuating devices in accordance with the manufacturer's specifications.
- Test functioning of all initiating devices.
- Inspect and exercise all supervised control valves and switches.
- Tag devices as required and perform all required record keeping.
- Compile a complete report of the inspection, explaining deficiencies and the recommended course of action needed. Technicians name and date of inspection must be included.
- Any testing must be proceeded with a contact to all persons receiving alarms and trouble signal to prevent unnecessary responses. Notify these same people when testing is complete.
- Test detector sensitivity.
- Sensitivity testing to be conducted annually for all of the smoke detectors.
- Cleaning of all of the smoke detectors and other initiating devices shall occur semi-annually.
- Record all sensitivity levels per the device.
- Label all smoke heads to correspond with Annunciator panels and reprogram Annunciator if required.
- Written Reports must be typed with all faults highlighted.

SPECIFICATIONS – PUBLIC ADDRESS/CLOCK SYSTEM MAINTENANCE: The contractor shall furnish all labor, personnel, materials and services required to perform the necessary maintenance and repairs to the public address system/clocks equipment located in the District’s properties. In the event of a malfunction, the vendor shall respond within two (2) hours. The contractor must get a service ticket signed by the head custodian and leave a copy in order to get paid.

Public Address Systems are located in five school buildings with the District. They are listed below:

- | | |
|--|---|
| 1. Evans Park Elementary School
40 Marion Place
Pearl River, NY 10965 | 2. Franklin Avenue Elementary School
48 Franklin Avenue
Pearl River, NY 10965 |
| 3. Lincoln Avenue Elementary School
115 Lincoln Avenue
Pearl River, NY 10965 | 4. Pearl River Middle School
520 Gilbert Avenue
Pearl River, NY 10965 |
| 5. Pearl River High School
275 East Central Avenue
Pearl River, NY 10965 | |

SITE VISITATION: For further information and/or field visitation contact Bob Nelan, Director of Facilities for appointment at 845-620-3856

THE BOARD OF EDUCATION RESERVES THE RIGHT TO REJECT ANY OR ALL BIDS

Pearl River Union Free School District, Pearl River, NY 10965
Burglar Alarm Equipment Monitoring, Maintenance & Inspection
BID FORM

Burglar Alarm System Monitoring, Maintenance & Inspection

1. Lump sum – Yearly Testing – Seven Building Locations:

\$ _____

2. Lump sum – Burglar Alarm Monitoring – Seven Building Locations:

\$ _____

3. Maintenance hourly rate as per prevailing wage (wages + supplemental benefits). Rate must include all travel costs and shall be per man.

A: Monday - Friday
8.00am – 5.00pm _____ \$ _____
(Words) (Numbers)

B: Monday - Friday
5.00pm – 11.00pm _____ \$ _____
(Words) (Numbers)

C: Saturday _____ \$ _____
(Words) (Numbers)

D: Sunday _____ \$ _____
(Words) (Numbers)

4. Materials: Percent of markup

Unit cost plus _____%

Submitted by:

Company name

Address

City, State, Zip

(Print name)

(Signature)

(Phone)

(Fax)

Pearl River Union Free School District, Pearl River, NY 10965
Fire Alarm Equipment Monitoring, Maintenance & Inspection
BID FORM

Burglar Alarm System Monitoring, Maintenance & Inspection

1. Lump sum - Yearly Inspection - Eight Building Locations:

\$ _____

2. Lump sum - Fire Alarm Monitoring - Eight Building Locations:

\$ _____

3. Maintenance hourly rate as per prevailing wage (wages + supplemental benefits). Rate must include all travel costs and shall be per man.

A: Monday - Friday
8.00am - 5.00pm _____ \$ _____
(Words) (Numbers)

B: Monday - Friday
5.00pm - 11.00pm _____ \$ _____
(Words) (Numbers)

C: Saturday _____ \$ _____
(Words) (Numbers)

D: Sunday _____ \$ _____
(Words) (Numbers)

4. Materials: Percent of markup

Unit cost plus _____%

Submitted by:

Company name

Address

City, State, Zip

(Print name) **(Signature)**

(Phone) **(Fax)**

PEARL RIVER SCHOOLS - EVANS PARK ELEMENTARY SCHOOL
40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT



Date: 8-2-17

Techs: CN/DB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-1		CORRIDOR OUTSIDE ROOM 18	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-2		ALL PURPOSE ROOM 44	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-3		ALL PURPOSE ROOM 44	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-4		ALL PURPOSE ROOM 44	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-5		ALL PURPOSE ROOM 44	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-6		CAFETERIA 43	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-7		CAFETERIA 43	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-8		CAFETERIA 43	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-9		CAFETERIA 43	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-10		CORRIDOR OUTSIDE CAFETERIA	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-11		CORRIDOR OUTSIDE ROOM 11	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-12		CORRIDOR OUTSIDE ROOM 17	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-13		CORRIDOR OUTSIDE ROOM 36	[√] PASS [] FAIL N/A [] VISUAL []

PEARL RIVER SCHOOLS - EVANS PARK ELEMENTARY SCHOOL
40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT



Date: 8-2-17

Techs: CN/DB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-14		CORRIDOR OUTSIDE ROOM 8A	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-15		CORRIDOR OUTSIDE ROOM 7	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-16		CORRIDOR OUTSIDE ROOM 5	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-17		CORRIDOR OUTSIDE ROOM 36	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-18		CORRIDOR OUTSIDE ROOM 1	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-19		STORAGE 6A	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-20		LIBRARY 14	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-21		LIBRARY 14	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-22		CORRIDOR OUTSIDE OFFICE ROOM 30	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-23		CORRIDOR OUTSIDE ROOM 10	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-24		CORRIDOR OUTSIDE ROOM 12	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-25		LOBBY AT STORAGE 26	[√] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-26		CORRIDOR OUTSIDE BOYS BATHROOM 25	[√] PASS [] FAIL N/A [] VISUAL []

PEARL RIVER SCHOOLS - EVANS PARK ELEMENTARY SCHOOL
40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT



Date: 8-2-17

Techs: CN/DB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-27		CORRIDOR OUTSIDE ROOM 14	☒ PASS ☐ FAIL N/A ☐ VISUAL ☐
SMOKE DETECTOR	1-28		CORRIDOR OUTSIDE ROOM 16	☒ PASS ☐ FAIL N/A ☐ VISUAL ☐
SMOKE DETECTOR	1-29		CORRIDOR OUTSIDE ROOM 20	☒ PASS ☐ FAIL N/A ☐ VISUAL ☐
SMOKE DETECTOR	1-30		CORRIDOR OUTSIDE ROOM 22	☒ PASS ☐ FAIL N/A ☐ VISUAL ☐
HEAT DETECTOR	1-31		BOILER ROOM 35	☐ PASS ☐ FAIL N/A ☐ VISUAL ☒
HEAT DETECTOR	1-32		BOILER ROOM 35	☐ PASS ☐ FAIL N/A ☐ VISUAL ☒
HEAT DETECTOR	1-33		JANITOR CLOSET	☐ PASS ☐ FAIL N/A ☐ VISUAL ☒
HEAT DETECTOR	1-34		STORAGE 33	☐ PASS ☐ FAIL N/A ☐ VISUAL ☒
HEAT DETECTOR	1-35		STORAGE 35A	☐ PASS ☐ FAIL N/A ☐ VISUAL ☒
HEAT DETECTOR	1-36		STORAGE 41	☐ PASS ☐ FAIL N/A ☐ VISUAL ☒
HEAT DETECTOR	1-37		STORAGE	☐ PASS ☐ FAIL N/A ☐ VISUAL ☒
HEAT DETECTOR	1-38		STORAGE 45	☐ PASS ☐ FAIL N/A ☐ VISUAL ☒
HEAT DETECTOR	1-39		STORAGE 43A	☐ PASS ☐ FAIL N/A ☐ VISUAL ☒

PEARL RIVER SCHOOLS - EVANS PARK ELEMENTARY SCHOOL
40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT



Date: 8-2-17

Techs: CN/DB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-40		STORAGE 43A	[] PASS [] FAIL N/A [] VISUAL [√]
HEAT DETECTOR	1-41		STORAGE 43B	[] PASS [] FAIL N/A [] VISUAL [√]
HEAT DETECTOR	1-42		STORAGE 43A	[] PASS [] FAIL N/A [] VISUAL [√]
HEAT DETECTOR	1-43		JANITOR CLOSET	[] PASS [] FAIL N/A [] VISUAL [√]
HEAT DETECTOR	1-45		CLOSET 32	[] PASS [] FAIL N/A [] VISUAL [√]
HEAT DETECTOR	1-46		OFFICE 28	[] PASS [] FAIL N/A [] VISUAL [√]
PULL STATION	1-126		BOILER ROOM 35	[√] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-127		STORAGE	[√] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-128		CLASSROOM 18	[√] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-129		COORIDOR OUTSIDE ROOM 18	[√] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-130		ALL PURPOSE ROOM 44	[√] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-131		ALL PURPOSE ROOM 44	[√] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-132		ALL PURPOSE ROOM 44	[√] PASS [] FAIL N/A [] VISUAL []

PEARL RIVER SCHOOLS - EVANS PARK ELEMENTARY SCHOOL
40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT



Date: 8-2-17

Techs: CN/DB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	1-133		CAFETERIA 43	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-134		CAFETERIA 43	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-135		CAFETERIA KITCHEN	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-136		CORRIDOR OUTSIDE MAIN OFFICE	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-137		CORRIDOR OUTSIDE ROOM 8A	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-138		CORRIDOR OUTSIDE ROOM 1	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-139		CORRIDOR OUTSIDE ROOM 12	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-140		LOBBY AT STORAGE 26	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-141		CLASSROOM 14	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-143		CLASSROOM 13	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-145		CORRIDOR OUTSIDE ROOM 22	[☒] PASS [] FAIL N/A [] VISUAL []
CO DETECTOR	1-146		BOILER ROOM	[☒] PASS [] FAIL N/A [] VISUAL []
FAN SHUTDOWN			NOT TESTED	[] PASS [] FAIL N/A [☒] VISUAL []

**PEARL RIVER SCHOOLS - EVANS PARK ELEMENTARY SCHOOL
40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT**



Date: 8-2-17

Techs: CN/DB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
ELEVATOR RECALL			NONE	[] PASS [] FAIL N/A [✓] VISUAL []
CENTRAL STATION				[✓] PASS [] FAIL N/A [] VISUAL []
BATTERIES				[✓] PASS [] FAIL N/A [] VISUAL []
A/V TEST				PASS [✓] FAIL [] N/A []
PANEL STATUS			NORMAL	

PEARL RIVER SCHOOL DISTRICT - FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **8-2-17**
 Techs: **CN/DB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0001		CORRIDOR OUTSIDE ROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0002		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0003		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0004		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0005		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0006		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0007		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0008		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0009		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0010		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0011		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0012		CORRIDOR OUTSIDE NURSE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0013		CORRIDOR OUTSIDE BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

PEARL RIVER SCHOOL DISTRICT - FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **8-2-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0014		LOBBY/MAIN OFFICE 24	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0015		LOBBY/MAIN OFFICE 24	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0016		LOBBY/MAIN OFFICE 24	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0017		LIBRARY 15	PASS [] FAIL [] N/A [☒] VISUAL []
SMOKE DETECTOR	1-0018		LIBRARY 15	PASS [] FAIL [] N/A [☒] VISUAL []
SMOKE DETECTOR	1-0019		CORRIDOR AT LIBRARY 15	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0020		CORRIDOR OUTSIDE LIBRARY	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0021		CORRIDOR OUTSIDE ROOM 4	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0022		CORRIDOR OUTSIDE ROOM 3	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0023		CORRIDOR OUTSIDE ROOM 3	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0024		CORRIDOR OUTSIDE ROOM 5	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0025		CORRIDOR OUTSIDE ROOM 6	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0026		CORRIDOR OUTSIDE ROOM 10	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0027		CORRIDOR OUTSIDE ROOM 9	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0028		CORRIDOR OUTSIDE ROOM 7	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0029		CORRIDOR AT GIRLS 35	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0030		CORRIDOR AT JANITORS ROOM 36	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0031		CORRIDOR OUTSIDE BOYS ROOM 38	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0032		CORRIDOR OUTSIDE ROOM 20	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0033		CORRIDOR OUTSIDE ROOM 21	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0034		CORRIDOR OUTSIDE ROOM 22	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0035		BOILER ROOM 28	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0036		BOILER ROOM 28	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0037		CLOSET	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0038		CLOSET	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0039		KITCHEN 29	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]

PEARL RIVER SCHOOL DISTRICT - FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **8-2-17**
 Techs: **CN/DB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0040		KITCHEN 29	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0041		GYM/CAFÉ 23	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0042		STORAGE 23A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0043		CLOSET IN WORK ROOM 30	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0044		CLOSET IN OFFICE 24A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0045		CLOSET IN OFFICE 24A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0046		JANITOR 33	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0047		STORAGE 34	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0048		CLASSROOM 2	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0049		STORAGE 4A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0050		CLOSET IN CLASSROOM 5	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0051		CLOSET IN CLASSROOM 6	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0052		CLOSET IN CLASSROOM 12	PASS [] FAIL [] N/A [] VISUAL [☒]

PEARL RIVER SCHOOL DISTRICT - FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **8-2-17**
 Techs: **CN/DB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0053		CLOSET IN CLASSROOM 7	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0054		CLOSET IN CLASSROOM 8	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0055		CLOSET IN CLASSROOM 11	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0056		JANITOR 36	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0057		JANITOR 37	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0058		CLOSET IN CLASSROOM 18	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0059		CLOSET IN CLASSROOM 19	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0060		CLOSET IN CLASSROOM 20	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0061		CLOSET IN CLASSROOM 17	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0062		CLOSET IN CLASSROOM 21	PASS [] FAIL [] N/A [] VISUAL [√]
HEAT DETECTOR	1-0063		CLOSET IN CLASSROOM 22	PASS [] FAIL [] N/A [] VISUAL [√]
SMOKE DETECTOR	1-0064		CORRIDOR BY ROOM 19	PASS [√] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0065		CORRIDOR BY ROOM 27	PASS [√] FAIL [] N/A [] VISUAL []

PEARL RIVER SCHOOL DISTRICT - FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **8-2-17**
 Techs: **CN/DB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0066		CORRIDOR BY ROOM 28	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0067		CLOSET IN ROOM 21	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0126		BOILER ROOM 28	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0127		BOILER ROOM 29	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0128		KITCHEN 29	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0129		CORRIDOR OUTSIDE ROOM 1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0130		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0131		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0132		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0133		CORRIDOR OUTSIDE BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0134		LOBBY/MAIN OFFICE 24	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0135		CORRIDOR OUTSIDE ROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0136		CLASSROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

PEARL RIVER SCHOOL DISTRICT - FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **8-2-17**
 Techs: **CN/DB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	1-0137		CLASSROOM 3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0138		STORAGE 4A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0139		CLASSROOM 5	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0140		CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0141		CORRIDOR OUTSIDE ROOM 10	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0142		CLASSROOM 21	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0143		CLASSROOM 22	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	1-0144		BOILER ROOM 28	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0152		CORRIDOR BY ROOM 28	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0153		CORRIDOR BY ROOM 19	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
BATTERIES				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
A/V TEST				PASS [☒] FAIL [☐] N/A [☐]
ELEVATOR RECALL			NONE	PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-17**
 Techs: **CN/DB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
FAN SHUTDOWN			NOT TESTED	PASS [] FAIL [] N/A [☒] VISUAL []
CENTRAL STATION				PASS [☒] FAIL [] N/A [] VISUAL []
PANEL STATUS			NORMAL	

PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **8-1-17**
 Techs: **CN/DB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0001	FIRST	CORRIDOR AT BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0002	FIRST	CORRIDOR AT ROOM 130	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0003	FIRST	SPECIAL EDUCATION 132	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0004	FIRST	CORRIDOR AT ROOM 133	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0005	FIRST	CORRIDOR AT ROOM 135	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0006	FIRST	STAIR ST-2 AT ROOM 135	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0008	FIRST	CORRIDOR AT ROOM 115	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0009	FIRST	CORRIDOR AT ROOM 115	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0010	FIRST	ELEVATOR MACHINE ROOM EL1A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0011	FIRST	STAIR ST-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0012	FIRST	CORRIDOR AT ROOM 110	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0013	FIRST	CORRIDOR AT OFFICE 111	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0014	FIRST	STAIR ST-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0015	FIRST	CORRIDOR CENTER	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0016	FIRST	CORRIDOR AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0018	FIRST	STAIR ST-5 AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0019	FIRST	CORRIDOR AT ROOM 127	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0020	FIRST	CORRIDOR AT ROOM 124	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0021	FIRST	CORRIDOR AT ROOM 122	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0022	FIRST	CORRIDOR AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0023	FIRST	CORRIDOR AT ROOM 120	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0036	FIRST	CORRIDOR CR-2 ELEVATOR EL1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	1-0037	FIRST	AIR HAND 116A SUPPLY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	1-0038	FIRST	AIR HAND 116A RETURN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	1-0039	FIRST	OFFICE 112C RETURN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0043	FIRST	BOILER ROOM 116	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0044	FIRST	AIR HANDLER 116A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0045	FIRST	AIR HANDLER 116A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0046	FIRST	BOILER ROOM 116	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0047	FIRST	BOILER ROOM 116	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0048	FIRST	BOILER ROOM 116	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0049	FIRST	BOILER ROOM 116	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0050	FIRST	STORAGE 134B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0051	FIRST	STORAGE 134A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0052	FIRST	STORAGE 135B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0053	FIRST	STORAGE 135A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0054	FIRST	STORAGE 131A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0022	FIRST	STORAGE 109B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0056	FIRST	OFFICE 112C	PASS [] FAIL [] N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0057	FIRST	STORAGE 112A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0058	FIRST	JANITOR 122A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0059	FIRST	STORAGE 126A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0060	FIRST	STORAGE 119A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0061	FIRST	STORAGE 119A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0062	FIRST	STORAGE 118A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0064	FIRST	STORAGE 120A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	1-0065	FIRST	STORAGE 120A	PASS [] FAIL [] N/A [] VISUAL [☒]
PULL STATION	1-0126	FIRST	BOILER ROOM 116	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0127	FIRST	CORRIDOR AT BOILER ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0128	FIRST	SPECIAL EDUCATION 132	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0129	FIRST	TECHNICIAN ROOM 134	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0130	FIRST	CORRIDOR AT ROOM 134	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	1-0131	FIRST	STAIR ST-2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0132	FIRST	CORRIDOR AT ROOM 113	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0133	FIRST	CORRIDOR AT ROOM 128	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0134	FIRST	CORRIDOR AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0135	FIRST	CORRIDOR AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0136	FIRST	CORRIDOR AT ROOM 120	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0137	FIRST	STAGE 119	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	1-0152	FIRST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	1-0153	FIRST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0251	SECOND	CORRIDOR CR-2 ELEVATOR EL1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0252	SECOND	CORRIDOR AT CAFETERIA	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0253	SECOND	CORRIDOR AT CAFETERIA	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0254	SECOND	STAIR ST-2 AT ROOM 238	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	2-0256	SECOND	CORRIDOR AT ROOM 236	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0257	SECOND	CORRIDOR AT ROOM 234	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0258	SECOND	CORRIDOR AT ROOM 232	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0260	SECOND	FACULTY DINING 213B	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0261	SECOND	CAFETERIA 213	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0262	SECOND	CAFETERIA 213	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0263	SECOND	CAFETERIA 213	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0264	SECOND	CAFETERIA 213	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0265	SECOND	CAFETERIA 213	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0266	SECOND	CAFETERIA 213	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0267	SECOND	CORRIDOR AT COPY ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0268	SECOND	CORRIDOR AT OFFICE 205C	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0269	SECOND	MAIN OFFICE 205	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	2-0270	SECOND	COPY ROOM 205A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0271	SECOND	CORRIDOR AT OFFICE 210	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0272	SECOND	LIBRARY 211	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0273	SECOND	LIBRARY 211	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0274	SECOND	LIBRARY 211	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0275	SECOND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0276	SECOND	CORRIDOR AT PSYCHOLOGIST	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0277	SECOND	CORRIDOR AT MAIN OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0278	SECOND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0279	SECOND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0280	SECOND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0281	SECOND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0282	SECOND	CORRIDOR AT NURSE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	2-0283	SECOND	CORRIDOR AT TEACHER PREP	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0285	SECOND	STAIR ST-5 AT ROOM 228	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0286	SECOND	CORRIDOR AT ROOM 227	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0287	SECOND	CORRIDOR AT ROOM 225	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0288	SECOND	CORRIDOR AT ROOM 223	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0289	SECOND	CORRIDOR AT ROOM 218	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0290	SECOND	CORRIDOR AT ROOM 220	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0291	SECOND	CORRIDOR AT ROOM 219	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0292	SECOND	CORRIDOR AT ROOM 219	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0293	SECOND	CORRIDOR LINK TO GYM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0294	SECOND	CORRIDOR AT GIRLS LOCKER	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0295	SECOND	GIRLS LOCKER ROOM 201G	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0296	SECOND	GIRLS LOCKER ROOM 201G	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	2-0297	SECOND	CORRIDOR AT BOYS LOCKER	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0298	SECOND	STAIR ST-3	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0299	SECOND	BOYS LOCKER ROOM 201B	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0300	SECOND	BOYS LOCKER ROOM 201B	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0301	SECOND	CORRIDOR CR-6 ELEVATOR EL1	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	2-0302	SECOND	MECHANICAL ROOM 205B RETURN	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	2-0303	SECOND	MECHANICAL ROOM 205B SUPPLY	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	2-0304	SECOND	MECHANICAL ROOM 202 SUPPLY	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	2-0305	SECOND	MECHANICAL ROOM 202 RETURN	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	2-0306	SECOND	MECHANICAL ROOM 202 SUPPLY	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	2-0307	SECOND	MECHANICAL ROOM 202 SUPPLY	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	2-0308	SECOND	MECHANICAL ROOM 201M SUPPLY	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	2-0309	SECOND	MECHANICAL ROOM 201M RETURN	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	2-0310	SECOND	STORAGE 211A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0311	SECOND	JANITOR 231A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0312	SECOND	STORAGE 237A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0313	SECOND	DRY STORAGE 213E	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0314	SECOND	KITCHEN 213A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0315	SECOND	KITCHEN 213A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0316	SECOND	CLOSET IN OFFICE 250C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0317	SECOND	MECHANICAL ROOM 205B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0318	SECOND	CLOSET IN LIBRARY 211	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0319	SECOND	STORAGE 204	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0320	SECOND	STORAGE 205F	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0321	SECOND	STORAGE 203E	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	2-0322	SECOND	STORAGE 204A	PASS [] FAIL [] N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	2-0323	SECOND	JANITOR 222A	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	2-0324	SECOND	STORAGE 226A	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	2-0325	SECOND	MECHANICAL ROOM 202	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	2-0326	SECOND	MECHANICAL ROOM 202	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	2-0327	SECOND	STORAGE 202A	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	2-0328	SECOND	STORAGE 202A	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	3-0329	SECOND	P.E. OFFICE 201A	PASS [] FAIL [] N/A [] VISUAL [✓]
SMOKE DETECTOR	3-0331	FIRST	STAGE 119	PASS [✓] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	3-0332	FIRST	STAGE 119	PASS [✓] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	3-0333	FIRST	GYMNASIUM 201	PASS [] FAIL [] N/A [✓] VISUAL []
SMOKE DETECTOR	3-0334	FIRST	GYMNASIUM 201	PASS [] FAIL [] N/A [✓] VISUAL []
SMOKE DETECTOR	3-0335	FIRST	GYMNASIUM 201	PASS [] FAIL [] N/A [✓] VISUAL []
SMOKE DETECTOR	3-0336	FIRST	GYMNASIUM 201	PASS [] FAIL [] N/A [✓] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	3-0337	FIRST	GYMNASIUM 201	PASS [] FAIL [] N/A [☒] VISUAL []
SMOKE DETECTOR	3-0338	FIRST	GYMNASIUM 201	PASS [] FAIL [] N/A [☒] VISUAL []
SMOKE DETECTOR	3-0339	FIRST	GYMNASIUM 201	PASS [] FAIL [] N/A [☒] VISUAL []
SMOKE DETECTOR	3-0340	FIRST	GYMNASIUM 201	PASS [] FAIL [] N/A [☒] VISUAL []
SMOKE DETECTOR	3-0341	FIRST	GYMNASIUM 201	PASS [] FAIL [] N/A [☒] VISUAL []
SMOKE DETECTOR	3-0342	FIRST	STAIR ST-3	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	3-0343	FIRST	STORAGE 120C RETURN	PASS [] FAIL [] N/A [☒] VISUAL []
DUCT DETECTOR	3-0344	FIRST	STORAGE 120C SUPPLY	PASS [] FAIL [] N/A [☒] VISUAL []
HEAT DETECTOR	3-0345	FIRST	STORAGE 119B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	3-0346	FIRST	STORAGE 120B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	3-0347	FIRST	STORAGE 120C	PASS [] FAIL [] N/A [] VISUAL [☒]
PULL STATION	3-0376	SECOND	CORRIDOR AT ROOM 236	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	3-0377	SECOND	CORRIDOR AT ROOM 230	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	3-0378	SECOND	KITCHEN 213A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0379	SECOND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0380	SECOND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0381	SECOND	CORRIDOR AT CAFETERIA	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0382	SECOND	CORRIDOR AT MECHANICAL ROOM 205B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0383	SECOND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0384	SECOND	CORRIDOR AT MAIN ENTRANCE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0385	SECOND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0386	SECOND	CORRIDOR AT ROOM 228	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0387	SECOND	CORRIDOR AT ROOM 224	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0388	SECOND	CORRIDOR AT ROOM 221	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0389	SECOND	CORRIDOR AT GIRLS LOCKER	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0390	SECOND	CORRIDOR AT BOYS LOCKER	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER MIDDLE SCHOOL
520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	3-0391	SECOND	BOYS LOCKER ROOM 201B	PASS ☒ FAIL ☐ N/A ☐ VISUAL ☐
PULL STATION	3-0400	FIRST	GYMNASIUM 201	PASS ☐ FAIL ☐ N/A ☒ VISUAL ☐
PULL STATION	3-0401	FIRST	GYMNASIUM 201	PASS ☐ FAIL ☐ N/A ☒ VISUAL ☐
PULL STATION	3-0402	FIRST	GYMNASIUM 201	PASS ☐ FAIL ☐ N/A ☒ VISUAL ☐
PULL STATION	3-0403	FIRST	GYMNASIUM 201	PASS ☐ FAIL ☐ N/A ☒ VISUAL ☐
PULL STATION	3-0404	FIRST	WRESTLING ROOM 120B	PASS ☐ FAIL ☐ N/A ☒ VISUAL ☐
PULL STATION	3-0405	FIRST	STAIR ST-3	PASS ☒ FAIL ☐ N/A ☐ VISUAL ☐
BATTERIES				PASS ☒ FAIL ☐ N/A ☐ VISUAL ☐
A/V TEST				PASS ☒ FAIL ☐ N/A ☐
ELEVATOR RECALL			NOT TESTED	PASS ☐ FAIL ☐ N/A ☒ VISUAL ☐
FAN SHUTDOWN				PASS ☒ FAIL ☐ N/A ☐ VISUAL ☐
CENTRAL STATION				PASS ☒ FAIL ☐ N/A ☐ VISUAL ☐
PANEL STATUS			NORMAL	

PEARL RIVER SCHOOL DISTRICT - STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0001	FIRST	CORRIDOR BY OFFICE 9A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0002	FIRST	BY CLASSROOM 8B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0003	FIRST	BY CLASSROOM 8B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0004	FIRST	CORRIDOR BY CLASSROOM 8A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0005	FIRST	LOBBY L-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0006	FIRST	CORRIDOR BY OFFICE 8D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0007	FIRST	CORRIDOR BY CLASSROOM 1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0008	FIRST	CORRIDOR BY CLASSROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0009	FIRST	CORRIDOR BY CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0010	FIRST	CORRIDOR BY CLASSROOM 7	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0011	FIRST	THERAPY 7A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0012	FIRST	CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0013	FIRST	CLASSROOM 5	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

PEARL RIVER SCHOOL DISTRICT - STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0014	FIRST	CLASSROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0015	FIRST	CLASSROOM 3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0016	FIRST	CLASSROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0017	FIRST	CLASSROOM 1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0018	FIRST	LOBBY L-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0019	FIRST	CORRIDOR BY CONFERENCE ROOM 10	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0020	FIRST	CORRIDOR BY THERAPY 10B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0021	FIRST	CORRIDOR BY OFFICE 17	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0022	FIRST	CORRIDOR BY OFFICE 17B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0023	FIRST	CORRIDOR BY GARAGE G-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0024	FIRST	CORRIDOR BY GARAGE G-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0025	FIRST	CORRIDOR BY JANITOR 20B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0026	FIRST	CORRIDOR BY STORAGE 24	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0027	FIRST	CORRIDOR BY STORAGE 21	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0028	GROUND	BY TRANS OFFICE ENTRY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0029	FIRST	CORRIDOR BY OFFICE 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0030	FIRST	STORAGE ROOM 9E	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0031	FIRST	MECHANICAL ROOM 9F	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	1-0032	FIRST	JANITOR CLOSET BY SHOP	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0033	FIRST	STORAGE ROOM 10A	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0034	FIRST	STORAGE ROOM 22	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0035	FIRST	CLOSET	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0036	FIRST	STORAGE ROOM 24	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0037	FIRST	STORAGE ROOM 23	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0038	FIRST	STORAGE ROOM 21	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0039	FIRST	WORK SHOP 20	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]

PEARL RIVER SCHOOL DISTRICT - STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0040	FIRST	WORK SHOP 20	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0041	FIRST	GARAGE G-1	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0042	FIRST	GARAGE G-1	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0043	FIRST	JANITOR CLOSET 20B	PASS [] FAIL [] N/A [] VISUAL [✓]
SMOKE DETECTOR	1-0044	FIRST	SMALL ARCHIVES STORAGE	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0045	GROUND	STORAGE ROOM 23	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0046	GROUND	STORAGE ROOM 23	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0047	GROUND	BOILER ROOM 6	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0048	FIRST	STORAGE ROOM 23	PASS [] FAIL [] N/A [] VISUAL [✓]
SMOKE DETECTOR	1-0049	FIRST	LARGE ARCHIVES STORAGE	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	1-0126	FIRST	MECHANICAL ROOM 9F	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	1-0127	FIRST	CORRIDOR BY OFFICE 9A	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	1-0128	FIRST	LOBBY L-1	PASS [✓] FAIL [] N/A [] VISUAL []

PEARL RIVER SCHOOL DISTRICT - STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	1-0129	FIRST	CORRIDOR BY OFFICE 8D	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0130	FIRST	CORRIDOR BY CLASSROOM 7	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0131	FIRST	CLASSROOM 1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0132	FIRST	LOBBY L-1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0133	FIRST	VESTIBULE BY TOILET 10C	PASS [] FAIL [] N/A [☒] VISUAL []
PULL STATION	1-0134	FIRST	CORRIDOR BY GARAGE G-1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0135	FIRST	CORRIDOR BY JANITOR 20B	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0136	FIRST	CORRIDOR BY STORAGE ROOM 24	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0137	FIRST	CORRIDOR BY STORAGE ROOM 21	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0138	FIRST	GARAGE G-1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0139	GROUND	CORRIDOR BY OFFICE 23	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0140	GROUND	SHOP EXIT EAST	PASS [☒] FAIL [] N/A [] VISUAL []
CO DETECTOR	1-0141	FIRST	MECHANICAL ROOM 9F	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **7-31-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
CO DETECTOR	1-0142	GROUND	BOILER ROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
BATTERIES				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
A/V TEST				PASS [☒] FAIL [☐] N/A [☐]
ELEVATOR RECALL			NONE	PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
FAN SHUTDOWN			NOT TESTED	PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
CENTRAL STATION				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PANEL STATUS			NORMAL	

**PEARL RIVER SCHOOL DISTRICT - ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **7-31-17**
Techs: **CN/DB**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION		BSMT	CORRIDOR EXIT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		BSMT	INSIDE ARCHIVES	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE LAUNDRY ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR		BSMT	CORRIDOR OUTSIDE LAUNDRY ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE OFFICE	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE OFFICE	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE WOMENS ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE MENS ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE FILE ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE CLOSET	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE CONFERENCE ROOM 'B'	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR		BSMT	CORRIDOR OUTSIDE FILE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		BSMT	INSIDE MAIL ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **7-31-17**
Techs: **CN/DB**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR		BSMT	INSIDE MAINTENANCE OFFICE	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR		BSMT	INSIDE MAINTENANCE OFFICE	PASS [] FAIL [] N/A [] VISUAL [✓]
SMOKE DETECTOR		BSMT	CORRIDOR OUTSIDE CONFERENCE ROOM 'A'	PASS [✓] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR		BSMT	INSIDE IT ROOM	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION		BSMT	OUTSIDE IT ROOM	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION		BSMT	NEAR STAIRS	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION		BSMT	INSIDE FILE ROOM	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION		BSMT	INSIDE FILE ROOM	PASS [✓] FAIL [] N/A [] VISUAL []
HEAT DETECTOR		BSMT	INSIDE STORAGE ROOM	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR		BSMT	INSIDE SHOP	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR		BSMT	INSIDE BOILER ROOM	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR		FIRST	INSIDE ASSISTANT SUPERINTENDENT	PASS [] FAIL [] N/A [] VISUAL [✓]
PULL STATION		FIRST	OUTSIDE SUPERINTENDENT	PASS [✓] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **7-31-17**
Techs: **CN/DB**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION		FIRST	MAIN ENTRANCE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		FIRST	MAIN LOBBY	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	MAIN LOBBY	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE BOARD ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE BOARD ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE KITCHEN	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE KITCHEN	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION		FIRST	OUTSIDE BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		FIRST	INSIDE STORAGE ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR		FIRST	OUTSIDE BATHROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		FIRST	INSIDE HUMAN RESOURCES	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE CONFERENCE ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE COPY ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **7-31-17**
Techs: **CN/DB**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR		FIRST	CORRIDOR OUTSIDE COPY ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR		FIRST	CORRIDOR OUTSIDE SUPERINTENDENT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		FIRST	INSIDE OFFICE CLOSET	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE OFFICE BATHROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE OFFICE	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE OFFICE	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE ASSISTANT SUPERINTENDENT	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE ASSISTANT SUPERINTENDENT	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE ASSISTANT SUPERINTENDENT	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION		BSMT	OUTSIDE BOILER ROOM EXIT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION		FIRST	NEAR STAIRS	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR		FIRST	CORRIDOR NEAR STAIRS	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		FIRST	INSIDE SERVER ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **7-31-17**
Techs: **CN/DB**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR		FIRST	INSIDE BUSINESS OFFICE	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE BUSINESS OFFICE	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE BUSINESS OFFICE	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE BUSINESS OFFICE	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE BUSINESS OFFICE	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE BUSINESS OFFICE	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE HUMAN RESOURCES	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE HUMAN RESOURCES	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE MENS ROOM	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE WOMENS ROOM	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE SLOP SINK ROOM	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE COAT CLOSET	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE KITCHEN	PASS [] FAIL [] N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **7-31-17**
Techs: **CN/DB**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR		FIRST	INSIDE CONFERENCE ROOM	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR		FIRST	INSIDE LIBRARY	PASS [] FAIL [] N/A [] VISUAL [☒]
PULL STATION		SECOND	NEAR STAIR 1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION		SECOND	NEAR STAIR 2	PASS [☒] FAIL [] N/A [] VISUAL []
BATTERIES				PASS [☒] FAIL [] N/A [] VISUAL []
A/V TEST				PASS [☒] FAIL [] N/A []
ELEVATOR RECALL			NONE	PASS [] FAIL [] N/A [☒] VISUAL []
FAN SHUTDOWN			NONE	PASS [] FAIL [] N/A [☒] VISUAL []
CENTRAL STATION				PASS [☒] FAIL [] N/A [] VISUAL []
PANEL STATUS			NORMAL	

**PEARL RIVER SCHOOL DISTRICT - LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0001		CORRIDOR AT CLASSROOM 19	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0002		CORRIDOR AT CLASSROOM 17	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0003		CORRIDOR AT CLASSROOM 15	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0004		CORRIDOR AT CLASSROOM 13	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0005		CORRIDOR AT LIBRARY 12	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0006		LIBRARY 12	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0007		LIBRARY 12	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0008		CORRIDOR AT KINDERGARTEN 10	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0009		CORRIDOR AT KINDERGARTEN 10	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0010		CORRIDOR BY SPEECH ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0011		CORRIDOR AT A/V ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0012		CLOSET BY A/V ROOM	PASS [] FAIL [] N/A [☒] VISUAL []
SMOKE DETECTOR	1-0013		CORRIDOR AT MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []

PEARL RIVER SCHOOL DISTRICT - LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0014		CORRIDOR AT MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0015		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0016		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0017		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0018		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0019		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0020		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0021		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0022		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0023		CORRIDOR AT MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0024		CORRIDOR AT MAIN OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0025		CORRIDOR AT GIRLS TOILET	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0026		CORRIDOR AT MAIN LOBBY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

PEARL RIVER SCHOOL DISTRICT - LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0027		CORRIDOR AT CLASSROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0028		CORRIDOR AT CLASSROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0029		CORRIDOR AT CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0030		BOILER ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0031		BOILER ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0032		BOILER ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0033		CLOSET BY BOILER ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0034		CLOSET IN LIBRARY	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0035		CLOSET IN KINDERGARTEN	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0036		JANITOR CLOSET BY KINDERGARTEN	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0037		STORAGE BY P.E. OFFICE	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0038		P.E. OFFICE	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0039		STORAGE IN KITCHEN	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0040		KITCHEN	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0041		KITCHEN	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0042		A/V ROOM	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0043		CLOSET BY LIBRARY	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0044		CLOSET BY MAIN OFFICE	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0045		CLOSET BY MAIN OFFICE	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0046		CLOSET BY MAIN OFFICE	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	1-0047		JANITOR CLOSET BY ENTRANCE	PASS [] FAIL [] N/A [] VISUAL [✓]
PULL STATION	1-0126		BOILER ROOM	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	1-0127		CORRIDOR AT CLASSROOM 19	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	1-0128		CORRIDOR AT BOILER ROOM	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	1-0129		CORRIDOR AT KINDERGARTEN 10	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	1-0130		KITCHEN	PASS [✓] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	1-0131		CORRIDOR AT A/V ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0132		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0133		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0134		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0135		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0136		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0137		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0138		CORRIDOR AT MAIN LOBBY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0139		CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0140		CLASSROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0141		CORRIDOR AT CLASSROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0142		CLASSROOM 5	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0143		CLASSROOM 3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **7-31-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
CO DETECTOR	1-0144		BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	1-0145		BOILER ROOM	PASS [☐] FAIL [☒] N/A [☐] VISUAL [☐]
BATTERIES			NEED TO BE REPLACED	PASS [☐] FAIL [☒] N/A [☐] VISUAL [☐]
A/V TEST				PASS [☒] FAIL [☐] N/A [☐]
ELEVATOR RECALL				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
FAN SHUTDOWN				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CENTRAL STATION				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PANEL STATUS			NORMAL	

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020001	FIRST	STAIR ST-2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020002	FIRST	STAIR ST-2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020003	FIRST	ELEVATOR LOBBY BY STAIR 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020004	FIRST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020005	FIRST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020006	FIRST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020007	FIRST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020008	FIRST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020009	FIRST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020010	FIRST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020011	FIRST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020012	FIRST	DOCUTEC CORRIDOR	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020013	FIRST	DOCUTEC CORRIDOR	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020014	FIRST	DOCUTEC ROOM 108	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020015	FIRST	PSYCH NEAR POLICE	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020016	FIRST	CORRIDOR OUTSIDE MEETING 107	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020017	FIRST	CORRIDOR OUTSIDE MEETING 107	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020018	FIRST	CORRIDOR AT KITCHEN STORAGE	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020019	FIRST	CORRIDOR AT KITCHEN	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020020	FIRST	CORRIDOR AT SERVING AREA	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020021	FIRST	CAFETERIA 105	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020022	FIRST	CAFETERIA 105	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020023	FIRST	CAFETERIA 105	PASS [☒] FAIL [] N/A [] VISUAL []
HEAT DETECTOR	01020024	FIRST	STAFF DINING 105B	PASS [] FAIL [] N/A [] VISUAL [☒]
SMOKE DETECTOR	01020025	FIRST	VESTIBULE V-1	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020026	FIRST	LOBBY OUTSIDE VESTIBULE V-1	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020027	FIRST	LOBBY OUTSIDE VESTIBULE V-1	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020028	FIRST	CAFETERIA 105	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020029	FIRST	ELEVATOR MACHINE ROOM EL1A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020030	FIRST	CORRIDOR AT CAFETERIA EXIT	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020031	FIRST	CORRIDOR AT OFFICE 103	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020032	FIRST	CORRIDOR AT ROOM 101	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020033	FIRST	POLICE	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020034	FIRST	CORRIDOR AT ROOM 100	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020035	FIRST	CORRIDOR AT ROOM 112	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020036	FIRST	CORRIDOR AT ROOM 112	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020037	FIRST	STAIR ST-3	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020038	FIRST	CORRIDOR AT ADMIN 113	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020039	FIRST	CORRIDOR AT CONFERENCE ROOM 115	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020040	FIRST	CORRIDOR OUTSIDE STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020041	FIRST	CORRIDOR OUTSIDE STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020042	FIRST	CAFETERIA EXIT 105A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020043	FIRST	CAFETERIA EXIT 105A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020044	FIRST	VIDEO LAB	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020045	FIRST	STAIR ST-1	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020046	FIRST	ELEVATOR LOBBY	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020047	FIRST	SUPPLY STORAGE 105C	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020048	FIRST	RETURN STORAGE 105C	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020049	FIRST	RETURN STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020050	FIRST	SUPPLY STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020051	FIRST	RETURN BOILER ROOM 104A	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020052	FIRST	SUPPLY BOILER ROOM 104A	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01020053	FIRST	STORAGE 105C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020054	FIRST	STORAGE 105C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020055	FIRST	STORAGE 105E	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020056	FIRST	SERVING 105D	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020057	FIRST	SERVING 105D	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020058	FIRST	KITCHEN STORAGE 106A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020059	FIRST	KITCHEN 106	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020060	FIRST	KITCHEN 106	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020061	FIRST	LOCKERS 106E	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020062	FIRST	KITCHEN STORAGE 106C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020063	FIRST	KITCHEN STORAGE 106B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020064	FIRST	KITCHENETTE 107B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01020065	FIRST	ELECTRICAL ROOM 107C	PASS [] FAIL [] N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01020066	FIRST	STORAGE ROOM 107E	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	01020067	FIRST	STORAGE ROOM 115A	PASS [] FAIL [] N/A [] VISUAL [✓]
SMOKE DETECTOR	01020068	FIRST	OFFICE 100B	PASS [✓] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020069	FIRST	CLASSROOM 104	PASS [✓] FAIL [] N/A [] VISUAL []
HEAT DETECTOR	01020071	FIRST	SCIENCE ROOM 104	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	01020072	FIRST	BOILER ROOM 104A	PASS [] FAIL [] N/A [] VISUAL [✓]
HEAT DETECTOR	01020073	FIRST	BOILER ROOM 104A	PASS [] FAIL [] N/A [] VISUAL [✓]
PULL STATION	01020126	FIRST	ELEVATOR LOBBY BY STAIR 2	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01020127	FIRST	DOCUTECK CORRIDOR	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01020128	FIRST	KITCHEN 106	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01020129	FIRST	CORRIDOR OUTSIDE MEETING 107	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01020130	FIRST	CORRIDOR OUTSIDE MEETING 107	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01020131	FIRST	CORRIDOR AT KITCHEN STORAGE	PASS [✓] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01020132	FIRST	LOBBY OUTSIDE VESTIBULE 1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020133	FIRST	LOBBY OUTSIDE VESTIBULE 1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020134	FIRST	CORRIDOR CR-2 REAR EXIT	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020135	FIRST	CORRIDOR CR-1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020136	FIRST	CORRIDOR OUTSIDE STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020137	FIRST	VESTIBULE V-2	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020138	FIRST	SCIENCE ROOM 104	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020139	FIRST	BOILER ROOM 104A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020140	FIRST	BOILER ROOM 104A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020141	FIRST	STAIR ST-1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020143	FIRST	ROOM 108 DOCUTECH	PASS [☒] FAIL [] N/A [] VISUAL []
CO DETECTOR	01020150	FIRST	STORAGE ROOM 115A	PASS [] FAIL [] N/A [] VISUAL [☒]
CO DETECTOR	01020151	FIRST	BOILER ROOM 104A	PASS [] FAIL [] N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020251	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020252	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020253	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020254	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020255	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020256	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020257	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020258	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020259	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020260	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020261	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020262	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020263	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020264	FIRST	GYM 109	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020265	FIRST	GYM 109	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020266	FIRST	GIRLS LOCKER ROOM 111	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020267	FIRST	GIRLS LOCKER ROOM 111	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020268	FIRST	FITNESS CENTER 109C	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020269	FIRST	FITNESS CENTER 109C	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020270	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020271	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020272	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020273	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020274	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020275	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020276	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020277	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020278	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020279	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020280	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020281	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020282	FIRST	STORAGE ROOM 110G	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020283	FIRST	STORAGE ROOM 110F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	01020284	FIRST	BOYS LOCKER ROOM 110	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	01020285	FIRST	BOYS LOCKER ROOM 110	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020286	FIRST	BOYS LOCKER ROOM 110	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020287	FIRST	RETURN GIRLS LOCKER ROOM 111C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020288	FIRST	SUPPLY GIRLS LOCKER ROOM 111C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020289	FIRST	RETURN STORAGE 109E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
DUCT DETECTOR	01020290	FIRST	SUPPLY STORAGE 109E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020291	FIRST	RETURN STORAGE 109F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020292	FIRST	SUPPLY STORAGE 109F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	01020293	FIRST	STORAGE 111G	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020294	FIRST	TRAINER 109D	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020295	FIRST	STORAGE ROOM 109E	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020297	FIRST	STORAGE ROOM 110H	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020298	FIRST	STORAGE ROOM 110H	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020299	FIRST	STORAGE ROOM 110H	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020300	FIRST	STORAGE ROOM 110H	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020301	FIRST	STORAGE ROOM 110H	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	01020304	FIRST	STORAGE ROOM 110F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020305	SECOND	STAIR ST-2 LANDING	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01020376	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020378	FIRST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020379	FIRST	GIRLS LOCKER ROOM 111	PASS [☐] FAIL [☒] N/A [☐] VISUAL [☐]
PULL STATION	01020380	FIRST	TRAINER 109D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020381	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020382	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020383	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020384	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020385	FIRST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020386	FIRST	STORAGE ROOM 109H	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	01020393	FIRST	STORAGE ROOM 109H	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION	01020396	FIRST	STORAGE ROOM 110F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030002	SECOND	OUTSIDE OFFICE 216	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030003	SECOND	VESTIBULE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030004	SECOND	CORRIDOR BY OFFICE 217	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030005	SECOND	CORRIDOR BY OFFICE 217	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030006	SECOND	CORRIDOR BY OFFICE 217	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030007	SECOND	CORRIDOR BY TOILET 217H	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030008	SECOND	CORRIDOR AT ROOM 217 NURSE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030009	SECOND	CORRIDOR AT JANITOR ROOM 218A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030010	SECOND	ELEVATOR LOBBY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030011	SECOND	STAIR ST-2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030013	SECOND	CORRIDOR AT ROOM 235	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030014	SECOND	CORRIDOR AT ROOM 235	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030015	SECOND	CORRIDOR AT ROOM 227	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030016	SECOND	CORRIDOR AT ROOM 226	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030017	SECOND	CORRIDOR AT ROOM 224	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030018	SECOND	CORRIDOR AT ROOM 222	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030019	SECOND	CORRIDOR AT ROOM 232	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030020	SECOND	CORRIDOR AT ROOM 221	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030021	SECOND	CORRIDOR AT ROOM 220	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030022	SECOND	CORRIDOR AT RESOURCE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030023	SECOND	CORRIDOR AT LIBRARY	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030024	SECOND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030025	SECOND	STAIR ST-1	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030027	SECOND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030029	SECOND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030030	SECOND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030031	SECOND	CORRIDOR AT BOYS ROOM 211B	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030032	SECOND	CORRIDOR AT OFFICE 211	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030033	SECOND	STAIR ST-3	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030034	SECOND	STAIR ST-3	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030035	SECOND	CORRIDOR AT ROOM 201	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030036	SECOND	CORRIDOR AT ROOM 202	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030037	SECOND	CORRIDOR AT ROOM 203	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030038	SECOND	CORRIDOR AT ROOM 206	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030039	SECOND	CORRIDOR AT ROOM 205	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01030040	SECOND	SUPPLY MECHANICAL ROOM 216A	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01030041	SECOND	RETURN MECHANICAL ROOM 216A	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01030042	SECOND	SUPPLY MECHANICAL ROOM 216A	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01030043	SECOND	RETURN MECHANICAL ROOM 216A	PASS [☒] FAIL [] N/A [] VISUAL []
HEAT DETECTOR	01030044	SECOND	OFFICE 216B	PASS [] FAIL [] N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01030045	SECOND	JANITOR CLOSET 218A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030046	SECOND	STORAGE 233A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030047	SECOND	STORAGE 218	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030048	SECOND	STORAGE 211A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030049	SECOND	STORAGE 201B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030050	SECOND	STORAGE 201A	PASS [] FAIL [] N/A [] VISUAL [☒]
PULL STATION	01030126	FIRST	BOILER ROOM BY FACP	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030127	FIRST	BOILER ROOM BY FACP	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030128	SECOND	VESTIBULE	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030129	SECOND	CORRIDOR AT NURSE 217	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030130	SECOND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030131	SECOND	CORRIDOR AT ROOM 235	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030132	SECOND	CORRIDOR AT ROOM 227	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01030133	SECOND	CORRIDOR AT ROOM 222	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030134	SECOND	CORRIDOR AT ROOM 221	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030135	SECOND	CORRIDOR AT LIBRARY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030136	SECOND	LIBRARY 219	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030137	SECOND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030138	SECOND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030139	SECOND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030140	SECOND	CORRIDOR AT ROOM 205	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030251	THIRD	CORRIDOR AT ROOM 302	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030252	THIRD	CORRIDOR AT ROOM 301	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030253	THIRD	CORRIDOR AT POLICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030254	THIRD	CORRIDOR AT BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030255	THIRD	CORRIDOR AT STORAGE BY BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030256	THIRD	CORRIDOR AT STORAGE 308C	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030257	THIRD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030258	THIRD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030259	THIRD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030260	THIRD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030261	THIRD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030262	THIRD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030263	THIRD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030264	THIRD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030265	THIRD	STAGE 303A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030266	THIRD	STAGE 303A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030267	THIRD	OUTSIDE STORAGE 303E	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030268	THIRD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030269	THIRD	STORAGE 303B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030270	THIRD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030271	THIRD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030272	THIRD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030273	THIRD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030274	THIRD	CORRIDOR AT JANITOR ROOM 307C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030275	THIRD	CORRIDOR AT JANITOR ROOM 307C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030276	THIRD	STAIR ST-4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030277	THIRD	STAIR ST-4 LANDING	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030278	THIRD	CORRIDOR CR-13 BY STAIR 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030279	THIRD	CORRIDOR CR-12 BY ROOM 311	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030280	THIRD	CORRIDOR CR-12 BY ROOM 311A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030281	THIRD	CORRIDOR CR-12 BY ROOM 319	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030282	THIRD	CORRIDOR CR-12 BY ROOM 317	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030283	THIRD	CORRIDOR CR-12 BY ROOM 316	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030284	THIRD	CORRIDOR CR-11 BY ROOM 311	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030285	THIRD	CORRIDOR CR-11 BY ROOM 311	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030286	THIRD	STAIR ST-2 LANDING	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030287	THIRD	STAIR ST-2	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030288	THIRD	ELEVATOR LOBBY	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030289	THIRD	CORRIDOR CR-10 BY ELEVATOR	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030290	THIRD	CORRIDOR CR-10 BY ROOM 330	PASS [☒] FAIL [] N/A [] VISUAL []
HEAT DETECTOR	01030292	THIRD	ART STORAGE ROOM	PASS [] FAIL [] N/A [] VISUAL [☒]
SMOKE DETECTOR	01030293	THIRD	CORRIDOR CR-9 BY ROOM 336	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030294	THIRD	CORRIDOR CR-9 BY ROOM 335A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030295	THIRD	CORRIDOR CR-9 BY STAIR 1	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030296	THIRD	STAIR ST-1	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030297	THIRD	STAIR ST-1 LANDING	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030298	THIRD	ELEVATOR SHAFT	PASS [] FAIL [] N/A [☒] VISUAL []
DUCT DETECTOR	01030299	THIRD	SUPPLY MUSIC 301B	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01030300	THIRD	RETURN MUSIC 301B	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01030301	THIRD	SUPPLY PRACTICE 302G	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01030302	THIRD	RETURN PRACTICE 302G	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01030303	THIRD	RETURN STORAGE 303E	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01030304	THIRD	SUPPLY STORAGE 303E	PASS [☒] FAIL [] N/A [] VISUAL []
HEAT DETECTOR	01030305	THIRD	CLOSET BY ELECTRICAL 300C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030306	THIRD	ELECTRIC/BOILER 300C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030307	THIRD	ELECTRIC/BOILER 300C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030308	THIRD	ELECTRIC/BOILER 300C	PASS [] FAIL [] N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01030309	THIRD	ELECTRIC/BOILER 300C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030310	THIRD	STORAGE ROOM 302C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030311	THIRD	STORAGE ROOM 302B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030312	THIRD	STORAGE ROOM 302A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030313	THIRD	STORAGE ROOM 306D	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030314	THIRD	STORAGE ROOM 306C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030315	THIRD	STORAGE ROOM 306B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030316	THIRD	STORAGE ROOM 306A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030317	THIRD	ROOM BY STORAGE 303B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030319	THIRD	ROOM BY STORAGE 303B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030320	THIRD	STORAGE ROOM 303F	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030321	THIRD	ROOM INSIDE STORAGE 303E	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030322	THIRD	STORAGE ROOM 303E	PASS [] FAIL [] N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01030323	THIRD	STORAGE ROOM 303C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030324	THIRD	STORAGE ROOM 305C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030325	THIRD	STORAGE ROOM 305B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030326	THIRD	JANITOR CLOSET 307B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030327	THIRD	JANITOR CLOSET 307C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030328	THIRD	STORAGE ROOM 312C	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030329	THIRD	STORAGE ROOM 312B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030330	THIRD	STORAGE ROOM 312A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030331	THIRD	STORAGE ROOM 311A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030332	THIRD	STORAGE ROOM 311B	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030333	THIRD	STORAGE ROOM 310A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030334	THIRD	STORAGE ROOM 335A	PASS [] FAIL [] N/A [] VISUAL [☒]
HEAT DETECTOR	01030335	THIRD	STORAGE ROOM 335B	PASS [] FAIL [] N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01030336	THIRD	STORAGE ROOM 330A	PASS [] FAIL [] N/A [] VISUAL [✓]
SMOKE DETECTOR	01030337	THIRD	CORRIDOR CR-11	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030376	THIRD	ELECTRIC/BOILER 300C	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030377	THIRD	COPY ROOM 300D	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030378	THIRD	INST. MUSIC 302	PASS [] FAIL [✓] N/A [] VISUAL []
PULL STATION	01030379	THIRD	CORRIDOR AT ROOM 302	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030380	THIRD	OUTSIDE ROOM 300C	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030381	THIRD	CORRIDOR AT BOILER ROOM	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030382	THIRD	AUDITORIUM 303	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030383	THIRD	AUDITORIUM 303	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030384	THIRD	AUDITORIUM 303	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030385	THIRD	AUDITORIUM 303	PASS [✓] FAIL [] N/A [] VISUAL []
PULL STATION	01030386	THIRD	STAGE 303A	PASS [✓] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01030387	THIRD	STAGE 303A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030388	THIRD	DRESSING ROOM 303D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030389	THIRD	DRESSING ROOM 303C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030390	THIRD	OUTSIDE STORAGE 303E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030391	THIRD	INDUS ART 303	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030392	THIRD	INDUS ART 303	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030393	THIRD	ART 304	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030394	THIRD	ART 304	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030395	THIRD	CORRIDOR AT JANITOR 307B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030396	THIRD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030397	THIRD	CORRIDOR AT JANITOR 307B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030398	THIRD	CORRIDOR AT CR-13 BY STAIR 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030399	THIRD	CORRIDOR AT ROOM 316	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**

Techs: **CN/DB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01030400	THIRD	CORRIDOR AT ELEVATOR EL1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030401	THIRD	CORRIDOR AT ROOM 332	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030402	THIRD	ROOM 335	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	01030403	THIRD	ELECTRIC/BOILER 300C	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	01020080	FIRST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020079	FIRST	MECHANICAL ROOM 108	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020078	FIRST	OFFICE 100A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020077	FIRST	OFFICE 100B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020076	FIRST	STORAGE 101A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020075	FIRST	CONFERENCE ROOM 101	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020074	FIRST	CLASSROOM 102	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020070	FIRST	CLASSROOM 103	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
BATTERIES			NEED TO BE REPLACED 2 - 12V 35AH	PASS [☐] FAIL [☒] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-11-17**
Techs: **CN/DB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
A/V TEST				PASS [☒] FAIL [☐] N/A [☐]
ELEVATOR RECALL			NOT TESTED	PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
FAN SHUTDOWN				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CENTRAL STATION				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PANEL STATUS			3 TROUBLES	

**PEARL RIVER SCHOOL DISTRICT - WILLIAMS STREET ARC SCHOOL
37 FRANKLIN AVENUE PEARL RIVER, NY 10595
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **SK 5808**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	004	FIRST	VESTIBULE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	013	FIRST	MAIN HALL #3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	010	FIRST	MAIN HALL #2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	014	FIRST	MAIN HALL #4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	007	FIRST	MAIN HALL #1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	005	FIRST	OFFICE HALLWAY #1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	006	FIRST	OFFICE HALLWAY #2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	008	FIRST	OFFICE HALLWAY #3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	009	FIRST	OFFICE HALLWAY #4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		FIRST	KITCHEN	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		FIRST	BOILER ROOM	PASS [☐] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION	003	FIRST	HALLWAY NORTH	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	002	FIRST	HALLWAY MIDDLE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT - WILLIAMS STREET ARC SCHOOL
37 FRANKLIN AVENUE PEARL RIVER, NY 10595
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-1-17**
Techs: **CN/DB**
System: **SK 5808**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	001	FIRST	HALLWAY SOUTH	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
BATTERIES				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
A/V TEST				PASS [☒] FAIL [☐] N/A [☐]
ELEVATOR RECALL			NONE	PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
FAN SHUTDOWN			NONE	PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
CENTRAL STATION				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PANEL STATUS			NORMAL	