

PEARL RIVER SCHOOL DISTRICT
RFB-PR-2018-15A BURGLAR/FIRE ALARM
& PA/CLOCK SYSTEM - REBID

ADDENDUM #1

To: ALARM SYSTEM VENDORS
From: Pearl River School District
Date: 7/21/2017
Re: ADDITIONAL SPECIFICATIONS

In response to a vendor's request for additional information, copies of the Fire Inspection Reports for 2016 for the district fire alarms is available on our website, as well as a copy of this addendum sheet. Follow the directions for downloading the bid documents to find the addendum and reports.

If you have any questions, please contact Alice McCafferty at 845-620-3908.

You must acknowledge receipt of this addendum in order for your completed bid to be considered by Pearl River School District. Please sign below as acknowledgement that you have received the complete addendum. This sheet must be returned as part of your proposal. This form may be faxed to 845-620-3934.

I acknowledge receipt of Addendum #1 for RFB-PR-2018-15A BURGLAR/FIRE ALARM & PA/CLOCK SYSTEM - REBID

Firm Name (Please type/print clearly)

Individual's Name (Please type/print clearly)

Date

Signature of Individual Above

**PEARL RIVER SCHOOL DISTRICT ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **OV**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION		BSMT	CORRIDOR EXIT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		BSMT	INSIDE ARCHIVES	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE LAUNDRY ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR		BSMT	CORRIDOR OUTSIDE LAUNDRY ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		BSMT	INSIDE OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE WOMENS ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE MENS ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE FILE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE CLOSET	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE CONFERENCE ROOM 'B'	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR		BSMT	CORRIDOR OUTSIDE FILE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		BSMT	INSIDE MAIL ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **OV**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR		BSMT	INSIDE MAINTENANCE OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE MAINTENANCE OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR		BSMT	CORRIDOR OUTSIDE CONFERENCE ROOM 'A'	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR		BSMT	INSIDE IT ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION		BSMT	OUTSIDE IT ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION		BSMT	NEAR STAIRS	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION		BSMT	INSIDE FILE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION		BSMT	INSIDE FILE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		BSMT	INSIDE STORAGE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE SHOP	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		BSMT	INSIDE BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE ASSISTANT SUPERINTENDENT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION		1ST	OUTSIDE SUPERINTENDENT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **OV**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION		1ST	MAIN ENTRANCE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		1ST	MAIN LOBBY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	MAIN LOBBY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE BOARD ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE BOARD ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE KITCHEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE KITCHEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION		1ST	OUTSIDE BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE STORAGE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR		1ST	OUTSIDE BATHROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		1ST	INSIDE HUMAN RESOURCES	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE CONFERENCE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE COPY ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **OV**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR		1ST	CORRIDOR OUTSIDE COPY ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR		1ST	CORRIDOR OUTSIDE SUPERINTENDENT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE OFFICE CLOSET	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE OFFICE BATHROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE ASSISTANT SUPERINTENDENT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE ASSISTANT SUPERINTENDENT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE ASSISTANT SUPERINTENDENT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION		BSMT	OUTSIDE BOILER ROOM EXIT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION		1ST	NEAR STAIRS	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR		1ST	CORRIDOR NEAR STAIRS	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		1ST	INSIDE SERVER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **OV**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR		1ST	INSIDE BUSINESS OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE BUSINESS OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE BUSINESS OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE BUSINESS OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE BUSINESS OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE BUSINESS OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE HUMAN RESOURCES	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE HUMAN RESOURCES	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE MENS ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE WOMENS ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE SLOP SINK ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE COAT CLOSET	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE KITCHEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT ADMINISTRATION BUILDING
135 WEST CROOKED HILL ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **OV**
System: **FIRE LITE**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR		1ST	INSIDE CONFERENCE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	INSIDE LIBRARY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION		2ND	NEAR STAIR 1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION		2ND	NEAR STAIR 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
BATTERIES				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
A/V TEST				YES [☒] NO [☐]
ELEVATOR RECALL				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
FAN SHUTDOWN				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
CENTRAL STATION				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PANEL STATUS			NORMAL	

**PEARL RIVER SCHOOL SCHOOL DISTRICT
EVANS PARK ELEMENTARY SCHOOL 40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT**

OPEN SYSTEMS

METRO

Date: 8-3-16

Techs: OV/PB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	Test Results
SMOKE DETECTOR	1-1		CORRIDOR OUTSIDE ROOM 18	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-2		ALL PURPOSE ROOM 44	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-3		ALL PURPOSE ROOM 44	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-4		ALL PURPOSE ROOM 44	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-5		ALL PURPOSE ROOM 44	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-6		CAFETERIA 43	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-7		CAFETERIA 43	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-8		CAFETERIA 43	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-9		CAFETERIA 43	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-10		CORRIDOR OUTSIDE CAFETERIA	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-11		CORRIDOR OUTSIDE ROOM 11	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-12		CORRIDOR OUTSIDE ROOM 17	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-13		CORRIDOR OUTSIDE ROOM 36	[☒] PASS [] FAIL N/A [] VISUAL []

**PEARL RIVER SCHOOL SCHOOL DISTRICT
EVANS PARK ELEMENTARY SCHOOL 40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT**



Date: 8-3-16

Techs: OV/PB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	Test Results
SMOKE DETECTOR	1-14		CORRIDOR OUTSIDE ROOM 8A	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-15		CORRIDOR OUTSIDE ROOM 7	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-16		CORRIDOR OUTSIDE ROOM 5	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-17		CORRIDOR OUTSIDE ROOM 36	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-18		CORRIDOR OUTSIDE ROOM 1	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-19		STORAGE 6A	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-20		LIBRARY 14	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-21		LIBRARY 14	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-22		CORRIDOR OUTSIDE OFFICE ROOM 30	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-23		CORRIDOR OUTSIDE ROOM 10	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-24		CORRIDOR OUTSIDE ROOM 12	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-25		LOBBY @ STORAGE 26	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-26		CORRIDOR OUTSIDE BOYS BATH 25	[☒] PASS [] FAIL N/A [] VISUAL []

PEARL RIVER SCHOOL SCHOOL DISTRICT
EVANS PARK ELEMENTARY SCHOOL 40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT

OPEN SYSTEMS

METRO

Date: 8-3-16

Techs: OV/PB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	Test Results
SMOKE DETECTOR	1-27		CORRIDOR OUTSIDE ROOM 14	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-28		CORRIDOR OUTSIDE ROOM 16	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-29		CORRIDOR OUTSIDE ROOM 20	[☒] PASS [] FAIL N/A [] VISUAL []
SMOKE DETECTOR	1-30		CORRIDOR OUTSIDE ROOM 22	[☒] PASS [] FAIL N/A [] VISUAL []
HEAT DETECTOR	1-31		BOILER ROOM 35	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-32		BOILER ROOM 35	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-33		JANITOR CLOSET	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-34		STORAGE 33	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-35		STORAGE 35A	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-36		STORAGE 41	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-37		STORAGE	[☒] PASS [] FAIL N/A [] VISUAL []
HEAT DETECTOR	1-38		STORAGE 45	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-39		STORAGE 43A	[☒] PASS [] FAIL N/A [] VISUAL [☒]

**PEARL RIVER SCHOOL SCHOOL DISTRICT
EVANS PARK ELEMENTARY SCHOOL 40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT**



Date: 8-3-16

Techs: OV/PB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	Test Results
HEAT DETECTOR	1-40		STORAGE 43A	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-41		STORAGE 43B	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-42		STORAGE 43A	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-43		JANITOR CLOSET	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-45		CLOSET 32	[☒] PASS [] FAIL N/A [] VISUAL [☒]
HEAT DETECTOR	1-46		OFFICE 28	[☒] PASS [] FAIL N/A [] VISUAL [☒]
PULL STATION	1-126		BOILER ROOM 35	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-127		STORAGE	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-128		CLASSROOM 18	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-129		COORIDOR OUTSIDE ROOM 18	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-130		ALL PURPOSE ROOM 44	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-131		ALL PURPOSE ROOM 44	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-132		ALL PURPOSE ROOM 44	[☒] PASS [] FAIL N/A [] VISUAL []

PEARL RIVER SCHOOL SCHOOL DISTRICT
EVANS PARK ELEMENTARY SCHOOL 40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT

OPEN SYSTEMS

METRO

Date: 8-3-16

Techs: OV/PB

System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	Test Results
PULL STATION	1-133		CAFETERIA 43	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-134		CAFETERIA 43	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-135		CAFETERIA KITCHEN	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-136		CORRIDOR OUTSIDE MAIN OFFICE	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-137		CORRIDOR OUTSIDE ROOM 8A	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-138		CORRIDOR OUTSIDE ROOM 1	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-139		CORRIDOR OUTSIDE ROOM 12	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-140		LOBBY AT STORAGE 26	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-141		CLASSROOM 14	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-143		CLASSROOM 13	[☒] PASS [] FAIL N/A [] VISUAL []
PULL STATION	1-145		CORRIDOR OUTSIDE ROOM 22	[☒] PASS [] FAIL N/A [] VISUAL []
CO DETECTOR	1-146		BOILER ROOM	[☒] PASS [] FAIL N/A [] VISUAL []
FAN SHUTDOWN				[] PASS [] FAIL N/A [☒] VISUAL []

**PEARL RIVER SCHOOL SCHOOL DISTRICT
EVANS PARK ELEMENTARY SCHOOL 40 MARION PLACE PEARL RIVER NY 10965
ANNUAL FIRE ALARM SYSTEM INSPECTION REPORT**

				Date: 8-3-16
				Techs: OV/PB
				System: EST-3
DEVICE	ADDRESS	FLOOR	LOCATION	Test Results
ELEVATOR RECALL				[] PASS [] FAIL N/A [√] VISUAL []
CENTRAL STATION				[] PASS [] FAIL N/A [√] VISUAL []
BATTERIES				[√] PASS [] FAIL N/A [] VISUAL []
A/V TEST				YES [√] NO []
PANEL STATUS			NORMAL	

**PEARL RIVER SCHOOL DISTRICT FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **PB OV**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0001		CORRIDOR OUTSIDE ROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0002		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0003		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0004		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0005		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0006		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0007		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0008		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0009		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0010		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0011		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0012		CORRIDOR OUTSIDE NURSE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0013		CORRIDOR OUTSIDE BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **PB OV**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0014		LOBBY/MAIN OFFICE 24	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0015		LOBBY/MAIN OFFICE 24	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0016		LOBBY/MAIN OFFICE 24	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0017		LIBRARY 15	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0018		LIBRARY 15	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0019		CORRIDOR AT LIBRARY 15	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0020		CORRIDOR OUTSIDE LIBRARY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0021		CORRIDOR OUTSIDE ROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0022		CORRIDOR OUTSIDE ROOM 3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0023		CORRIDOR OUTSIDE ROOM 3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0024		CORRIDOR OUTSIDE ROOM 5	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0025		CORRIDOR OUTSIDE ROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0026		CORRIDOR OUTSIDE ROOM 10	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **PB OV**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0027		CORRIDOR OUTSIDE ROOM 9	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0028		CORRIDOR OUTSIDE ROOM 7	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0029		CORRIDOR AT GIRLS 35	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0030		CORRIDOR AT JANITORS ROOM 36	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0031		CORRIDOR OUTSIDE BOYS ROOM 38	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0032		CORRIDOR OUTSIDE ROOM 20	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0033		CORRIDOR OUTSIDE ROOM 21	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0034		CORRIDOR OUTSIDE ROOM 22	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0035		BOILER ROOM 28	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0036		BOILER ROOM 28	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0037		CLOSET	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0038		CLOSET	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0039		KITCHEN 29	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **PB OV**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0040		KITCHEN 29	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0041		GYM/CAFÉ 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0042		STORAGE 23A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0043		CLOSET IN WORK ROOM 30	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0044		CLOSET IN OFFICE 24A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0045		CLOSET IN OFFICE 24A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0046		JANITOR 33	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0047		STORAGE 34	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0048		CLASSROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0049		STORAGE 4A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0050		CLOSET IN CLASSROOM 5	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0051		CLOSET IN CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0052		CLOSET IN CLASSROOM 12	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **PB OV**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0053		CLOSET IN CLASSROOM 7	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0054		CLOSET IN CLASSROOM 8	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0055		CLOSET IN CLASSROOM 11	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0056		JANITOR 36	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0057		JANITOR 37	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0058		CLOSET IN CLASSROOM 18	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0059		CLOSET IN CLASSROOM 19	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0060		CLOSET IN CLASSROOM 20	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0061		CLOSET IN CLASSROOM 17	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0062		CLOSET IN CLASSROOM 21	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0063		CLOSET IN CLASSROOM 22	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	1-0064		CORRIDOR BY ROOM 19	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0065		CORRIDOR BY ROOM 27	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **PB OV**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0066		CORRIDOR BY ROOM 28	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0067		CLOSET IN ROOM 21	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0126		BOILER ROOM 28	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0127		BOILER ROOM 29	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0128		KITCHEN 29	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0129		CORRIDOR OUTSIDE ROOM 1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0130		GYM/CAFÉ 23	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0131		GYM/CAFÉ 23	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0132		GYM/CAFÉ 23	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0133		CORRIDOR OUTSIDE BOILER ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0134		LOBBY/MAIN OFFICE 24	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0135		CORRIDOR OUTSIDE ROOM 4	PASS [] FAIL [] N/A [☒] VISUAL []
PULL STATION	1-0136		CLASSROOM 2	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **PB OV**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	1-0137		CLASSROOM 3	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0138		STORAGE 4A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0139		CLASSROOM 5	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0140		CLASSROOM 6	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0141		CORRIDOR OUTSIDE ROOM 10	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0142		CLASSROOM 21	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0143		CLASSROOM 22	PASS [☒] FAIL [] N/A [] VISUAL []
CO DETECTOR	1-0144		BOILER ROOM 28	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0152		CORRIDOR BY ROOM 28	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	1-0153		CORRIDOR BY ROOM 19	PASS [☒] FAIL [] N/A [] VISUAL []
BATTERIES				PASS [☒] FAIL [] N/A [] VISUAL []
A/V TEST				YES [☒] NO []
ELEVATOR RECALL				PASS [] FAIL [] N/A [☒] VISUAL []

**PEARL RIVER SCHOOL DISTRICT FRANKLIN AVENUE ELEMENTARY SCHOOL
48 FRANKLIN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**

OPEN SYSTEMS
METRO

Date: **8-4-16**
Techs: **PB OV**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
FAN SHUTDOWN				PASS [] FAIL [] N/A [☒] VISUAL []
CENTRAL STATION				PASS [☒] FAIL [] N/A [] VISUAL []
PANEL STATUS			NORMAL	

**PEARL RIVER SCHOOL DISTRICT LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-2-16**

Techs: **OV PB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0001		CORRIDOR AT CLASSROOM 19	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0002		CORRIDOR AT CLASSROOM 17	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0003		CORRIDOR AT CLASSROOM 15	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0004		CORRIDOR AT CLASSROOM 13	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0005		CORRIDOR AT LIBRARY 12	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0006		LIBRARY 12	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0007		LIBRARY 12	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0008		CORRIDOR AT KINDERGARTEN 10	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0009		CORRIDOR AT KINDERGARTEN 10	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0010		CORRIDOR BY SPEECH ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0011		CORRIDOR AT A/V ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0012		CLOSET BY A/V ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0013		CORRIDOR AT MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-2-16**
Techs: **OV PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0014		CORRIDOR AT MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0015		MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0016		MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0017		MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0018		MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0019		MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0020		MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0021		MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0022		MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0023		CORRIDOR AT MULTI-PURPOSE ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0024		CORRIDOR AT MAIN OFFICE	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0025		CORRIDOR AT GIRLS TOILET	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	1-0026		CORRIDOR AT MAIN LOBBY	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-2-16**

Techs: **OV PB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0027		CORRIDOR AT CLASSROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0028		CORRIDOR AT CLASSROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0029		CORRIDOR AT CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0030		BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0031		BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0032		BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0033		CLOSET BY BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0034		CLOSET IN LIBRARY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0035		CLOSET IN KINDERGARTEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0036		JANITOR CLOSET BY KINDERGARTEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0037		STORAGE BY P.E. OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0038		P.E. OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0039		STORAGE IN KITCHEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

PEARL RIVER SCHOOL DISTRICT LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION



Date: **8-2-16**

Techs: **OV PB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0040		KITCHEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0041		KITCHEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0042		A/V ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0043		CLOSET BY LIBRARY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0044		CLOSET BY MAIN OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0045		CLOSET BY MAIN OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0046		CLOSET BY MAIN OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0047		JANITOR CLOSET BY ENTRANCE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION	1-0126		BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0127		CORRIDOR AT CLASSROOM 19	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0128		CORRIDOR AT BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0129		CORRIDOR AT KINDERGARTEN 10	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0130		KITCHEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-2-16**

Techs: **OV PB**

System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	1-0131		CORRIDOR AT A/V ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0132		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0133		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0134		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0135		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0136		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0137		MULTI-PURPOSE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0138		CORRIDOR AT MAIN LOBBY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0139		CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0140		CLASSROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0141		CORRIDOR AT CLASSROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0142		CLASSROOM 5	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0143		CLASSROOM 3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT LINCOLN AVENUE ELEMENTARY SCHOOL
115 LINCOLN AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-2-16**
Techs: **OV PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
CO DETECTOR	1-0144		BOILER ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
CO DETECTOR	1-0145		BOILER ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
BATTERIES				PASS [☒] FAIL [] N/A [] VISUAL []
A/V TEST				YES [☒] NO []
ELEVATOR RECALL				PASS [] FAIL [] N/A [☒] VISUAL []
FAN SHUTDOWN				PASS [] FAIL [] N/A [☒] VISUAL []
CENTRAL STATION				PASS [☒] FAIL [] N/A [] VISUAL []
PANEL STATUS			IN TROUBLE; PHONE LINE 1	

PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION



Date: **8-1-16**
 Techs: **OV/PB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020001	1ST	STAIR ST-2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020002	1ST	STAIR ST-2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020003	1ST	ELEVATOR LOBBY BY STAIR 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020004	1ST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020005	1ST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020006	1ST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020007	1ST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020008	1ST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020009	1ST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020010	1ST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020011	1ST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020012	1ST	DOCUTEC CORRIDOR	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020013	1ST	DOCUTEC CORRIDOR	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020014	1ST	DOCUTEC ROOM 108	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020015	1ST	PSYCH NEAR POLICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020016	1ST	CORRIDOR OUTSIDE MEETING 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020017	1ST	CORRIDOR OUTSIDE MEETING 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020018	1ST	CORRIDOR AT KITCHEN STORAGE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020019	1ST	CORRIDOR AT KITCHEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020020	1ST	CORRIDOR AT SERVING AREA	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020021	1ST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020022	1ST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020023	1ST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	01020024	1ST	STAFF DINING 105B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	01020025	1ST	VESTIBULE V-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020026	1ST	LOBBY OUTSIDE VESTIBULE V-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020027	1ST	LOBBY OUTSIDE VESTIBULE V-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020028	1ST	CAFETERIA 105	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020029	1ST	ELEVATOR MACHINE ROOM EL1A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020030	1ST	CORRIDOR AT CAFETERIA EXIT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020031	1ST	CORRIDOR AT OFFICE 103	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020032	1ST	CORRIDOR AT ROOM 101	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020033	1ST	POLICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020034	1ST	CORRIDOR AT ROOM 100	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020035	1ST	CORRIDOR AT ROOM 112	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020036	1ST	CORRIDOR AT ROOM 112	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020037	1ST	STAIR ST-3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020038	1ST	CORRIDOR AT ADMIN 113	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020039	1ST	CORRIDOR AT CONFERENCE ROOM 115	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020040	1ST	CORRIDOR OUTSIDE STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020041	1ST	CORRIDOR OUTSIDE STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020042	1ST	CAFETERIA EXIT 105A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020043	1ST	CAFETERIA EXIT 105A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020044	1ST	VIDEO LAB	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020045	1ST	STAIR ST-1	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01020046	1ST	ELEVATOR LOBBY	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020047	1ST	SUPPLY STORAGE 105C	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020048	1ST	RETURN STORAGE 105C	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020049	1ST	RETURN STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020050	1ST	SUPPLY STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020051	1ST	RETURN BOILER ROOM 104A	PASS [☒] FAIL [] N/A [] VISUAL []
DUCT DETECTOR	01020052	1ST	SUPPLY BOILER ROOM 104A	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01020053	1ST	STORAGE 105C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020054	1ST	STORAGE 105C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020055	1ST	STORAGE 105E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020056	1ST	SERVING 105D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020057	1ST	SERVING 105D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020058	1ST	KITCHEN STORAGE 106A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020059	1ST	KITCHEN 106	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020060	1ST	KITCHEN 106	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020061	1ST	LOCKERS 106E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020062	1ST	KITCHEN STORAGE 106C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020063	1ST	KITCHEN STORAGE 106B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020064	1ST	KITCHENETTE 107B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020065	1ST	ELECTRICAL ROOM 107C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION



Date: **8-1-16**
 Techs: **OV/PB**
 System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01020066	1ST	STORAGE ROOM 107E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020067	1ST	STORAGE ROOM 115A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	01020068	1ST	OFFICE 100B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020069	1ST	CLASSROOM 104	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	01020071	1ST	SCIENCE ROOM 104	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020072	1ST	BOILER ROOM 104A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020073	1ST	BOILER ROOM 104A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION	01020126	1ST	ELEVATOR LOBBY BY STAIR 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020127	1ST	DOCUTECK CORRIDOR	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020128	1ST	KITCHEN 106	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020129	1ST	CORRIDOR OUTSIDE MEETING 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020130	1ST	CORRIDOR OUTSIDE MEETING 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01020131	1ST	CORRIDOR AT KITCHEN STORAGE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01020132	1ST	LOBBY OUTSIDE VESTIBULE 1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020133	1ST	LOBBY OUTSIDE VESTIBULE 1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020134	1ST	CORRIDOR CR-2 REAR EXIT	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020135	1ST	CORRIDOR CR-1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020136	1ST	CORRIDOR OUTSIDE STORAGE 115A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020137	1ST	VESTIBULE V-2	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020138	1ST	SCIENCE ROOM 104	PASS [] FAIL [] N/A [☒] VISUAL []
PULL STATION	01020139	1ST	BOILER ROOM 104A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020140	1ST	BOILER ROOM 104A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020141	1ST	STAIR ST-1	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020143	1ST	ROOM 108 DOCUTECH	PASS [☒] FAIL [] N/A [] VISUAL []
CO DETECTOR	01020150	1ST	STORAGE ROOM 115A	PASS [☒] FAIL [] N/A [] VISUAL []
CO DETECTOR	01020151	1ST	BOILER ROOM 104A	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020251	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020252	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020253	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020254	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020255	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020256	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020257	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020258	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020259	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020260	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020261	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020262	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020263	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020264	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020265	1ST	GYM 109	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020266	1ST	GIRLS LOCKER ROOM 111	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020267	1ST	GIRLS LOCKER ROOM 111	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020268	1ST	FITNESS CENTER 109C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020269	1ST	FITNESS CENTER 109C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020270	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020271	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020272	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020273	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020274	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020275	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020276	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01020277	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020278	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020279	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020280	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020281	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020282	1ST	STORAGE ROOM 110G	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020283	1ST	STORAGE ROOM 110F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	01020284	1ST	BOYS LOCKER ROOM 110	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	01020285	1ST	BOYS LOCKER ROOM 110	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020286	1ST	BOYS LOCKER ROOM 110	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020287	1ST	RETURN GIRLS LOCKER ROOM 111C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020288	1ST	SUPPLY GIRLS LOCKER ROOM 111C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020289	1ST	RETURN STORAGE 109E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
DUCT DETECTOR	01020290	1ST	SUPPLY STORAGE 109E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020291	1ST	RETURN STORAGE 109F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01020292	1ST	SUPPLY STORAGE 109F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	01020293	1ST	STORAGE 111G	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020294	1ST	TRAINER 109D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020295	1ST	STORAGE ROOM 109E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020297	1ST	STORAGE ROOM 110H	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020298	1ST	STORAGE ROOM 110H	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020299	1ST	STORAGE ROOM 110H	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020300	1ST	STORAGE ROOM 110H	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01020301	1ST	STORAGE ROOM 110H	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020304	1ST	STORAGE ROOM 110F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020305	2ND	STAIR ST-2 LANDING	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01020376	1ST	GYM 109	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020378	1ST	GYM 109	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020379	1ST	GIRLS LOCKER ROOM 111	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020380	1ST	TRAINER 109D	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020381	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020382	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020383	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020384	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020385	1ST	AUXILIARY GYM 109A	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020386	1ST	STORAGE ROOM 109H	PASS [☒] FAIL [] N/A [] VISUAL []
CO DETECTOR	01020393	1ST	STORAGE ROOM 109H	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01020396	1ST	STORAGE ROOM 110F	PASS [] FAIL [] N/A [☒] VISUAL []
SMOKE DETECTOR	01030002	2ND	OUTSIDE OFFICE 216	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030003	2ND	VESTIBULE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030004	2ND	CORRIDOR BY OFFICE 217	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030005	2ND	CORRIDOR BY OFFICE 217	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030006	2ND	CORRIDOR BY OFFICE 217	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030007	2ND	CORRIDOR BY TOILET 217H	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030008	2ND	CORRIDOR AT ROOM 217 NURSE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030009	2ND	CORRIDOR AT JANITOR ROOM 218A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030010	2ND	ELEVATOR LOBBY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030011	2ND	STAIR ST-2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030013	2ND	CORRIDOR AT ROOM 235	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030014	2ND	CORRIDOR AT ROOM 235	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030015	2ND	CORRIDOR AT ROOM 227	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030016	2ND	CORRIDOR AT ROOM 226	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030017	2ND	CORRIDOR AT ROOM 224	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030018	2ND	CORRIDOR AT ROOM 222	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030019	2ND	CORRIDOR AT ROOM 232	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030020	2ND	CORRIDOR AT ROOM 221	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030021	2ND	CORRIDOR AT ROOM 220	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030022	2ND	CORRIDOR AT RESOURCE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030023	2ND	CORRIDOR AT LIBRARY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030024	2ND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030025	2ND	STAIR ST-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030027	2ND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030029	2ND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030030	2ND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030031	2ND	CORRIDOR AT BOYS ROOM 211B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030032	2ND	CORRIDOR AT OFFICE 211	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030033	2ND	STAIR ST-3	PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
SMOKE DETECTOR	01030034	2ND	STAIR ST-3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030035	2ND	CORRIDOR AT ROOM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030036	2ND	CORRIDOR AT ROOM 202	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030037	2ND	CORRIDOR AT ROOM 203	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030038	2ND	CORRIDOR AT ROOM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030039	2ND	CORRIDOR AT ROOM 205	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030040	2ND	SUPPLY MECHANICAL ROOM 216A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030041	2ND	RETURN MECHANICAL ROOM 216A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030042	2ND	SUPPLY MECHANICAL ROOM 216A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030043	2ND	RETURN MECHANICAL ROOM 216A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	01030044	2ND	OFFICE 216B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01030045	2ND	JANITOR CLOSET 218A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030046	2ND	STORAGE 233A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030047	2ND	STORAGE 218	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030048	2ND	STORAGE 211A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030049	2ND	STORAGE 201B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030050	2ND	STORAGE 201A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION	01030126	1ST	BOILER ROOM BY FACP	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030127	1ST	BOILER ROOM BY FACP	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030128	2ND	VESTIBULE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030129	2ND	CORRIDOR AT NURSE 217	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030130	2ND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030131	2ND	CORRIDOR AT ROOM 235	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030132	2ND	CORRIDOR AT ROOM 227	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01030133	2ND	CORRIDOR AT ROOM 222	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030134	2ND	CORRIDOR AT ROOM 221	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030135	2ND	CORRIDOR AT LIBRARY	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030136	2ND	LIBRARY 219	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030137	2ND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030138	2ND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030139	2ND	CORRIDOR AT ROOM 200	PASS [☒] FAIL [] N/A [] VISUAL []
PULL STATION	01030140	2ND	CORRIDOR AT ROOM 205	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030251	3RD	CORRIDOR AT ROOM 302	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030252	3RD	CORRIDOR AT ROOM 301	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030253	3RD	CORRIDOR AT POLICE	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030254	3RD	CORRIDOR AT BOILER ROOM	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030255	3RD	CORRIDOR AT STORAGE BY BOILER ROOM	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030256	3RD	CORRIDOR AT STORAGE 308C	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030257	3RD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030258	3RD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030259	3RD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030260	3RD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030261	3RD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030262	3RD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030263	3RD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030264	3RD	AUDITORIUM 303	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030265	3RD	STAGE 303A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030266	3RD	STAGE 303A	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030267	3RD	OUTSIDE STORAGE 303E	PASS [☒] FAIL [] N/A [] VISUAL []
SMOKE DETECTOR	01030268	3RD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [] N/A [] VISUAL []

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030269	3RD	STORAGE 303B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030270	3RD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030271	3RD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030272	3RD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030273	3RD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030274	3RD	CORRIDOR AT JANITOR ROOM 307C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030275	3RD	CORRIDOR AT JANITOR ROOM 307C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030276	3RD	STAIR ST-4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030277	3RD	STAIR ST-4 LANDING	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030278	3RD	CORRIDOR CR-13 BY STAIR 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030279	3RD	CORRIDOR CR-12 BY ROOM 311	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030280	3RD	CORRIDOR CR-12 BY ROOM 311A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030281	3RD	CORRIDOR CR-12 BY ROOM 319	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030282	3RD	CORRIDOR CR-12 BY ROOM 317	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030283	3RD	CORRIDOR CR-12 BY ROOM 316	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030284	3RD	CORRIDOR CR-11 BY ROOM 311	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030285	3RD	CORRIDOR CR-11 BY ROOM 311	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030286	3RD	STAIR ST-2 LANDING	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030287	3RD	STAIR ST-2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030288	3RD	ELEVATOR LOBBY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030289	3RD	CORRIDOR CR-10 BY ELEVATOR	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030290	3RD	CORRIDOR CR-10 BY ROOM 330	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	01030292	3RD	ART STORAGE ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	01030293	3RD	CORRIDOR CR-9 BY ROOM 336	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030294	3RD	CORRIDOR CR-9 BY ROOM 335A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030295	3RD	CORRIDOR CR-9 BY STAIR 1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	01030296	3RD	STAIR ST-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030297	3RD	STAIR ST-1 LANDING	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01030298	3RD	ELEVATOR SHAFT	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030299	3RD	SUPPLY MUSIC 301B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030300	3RD	RETURN MUSIC 301B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030301	3RD	SUPPLY PRACTICE 302G	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030302	3RD	RETURN PRACTICE 302G	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030303	3RD	RETURN STORAGE 303E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	01030304	3RD	SUPPLY STORAGE 303E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	01030305	3RD	CLOSET BY ELECTRICAL 300C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030306	3RD	ELECTRIC/BOILER 300C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030307	3RD	ELECTRIC/BOILER 300C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030308	3RD	ELECTRIC/BOILER 300C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION



Date: **8-1-16**
 Techs: **OV/PB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01030309	3RD	ELECTRIC/BOILER 300C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030310	3RD	STORAGE ROOM 302C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030311	3RD	STORAGE ROOM 302B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030312	3RD	STORAGE ROOM 302A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030313	3RD	STORAGE ROOM 306D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030314	3RD	STORAGE ROOM 306C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030315	3RD	STORAGE ROOM 306B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030316	3RD	STORAGE ROOM 306A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030317	3RD	ROOM BY STORAGE 303B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030319	3RD	ROOM BY STORAGE 303B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030320	3RD	STORAGE ROOM 303F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030321	3RD	ROOM INSIDE STORAGE 303E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030322	3RD	STORAGE ROOM 303E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01030323	3RD	STORAGE ROOM 303C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030324	3RD	STORAGE ROOM 305C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030325	3RD	STORAGE ROOM 305B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030326	3RD	JANITOR CLOSET 307B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030327	3RD	JANITOR CLOSET 307C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030328	3RD	STORAGE ROOM 312C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030329	3RD	STORAGE ROOM 312B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030330	3RD	STORAGE ROOM 312A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030331	3RD	STORAGE ROOM 311A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030332	3RD	STORAGE ROOM 311B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030333	3RD	STORAGE ROOM 310A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030334	3RD	STORAGE ROOM 335A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	01030335	3RD	STORAGE ROOM 335B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	01030336	3RD	STORAGE ROOM 330A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	01030337	3RD	CORRIDOR CR-11	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030376	3RD	ELECTRIC/BOILER 300C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030377	3RD	COPY ROOM 300D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030378	3RD	INST. MUSIC 302	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030379	3RD	CORRIDOR AT ROOM 302	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030380	3RD	OUTSIDE ROOM 300C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030381	3RD	CORRIDOR AT BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030382	3RD	AUDITORIUM 303	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030383	3RD	AUDITORIUM 303	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030384	3RD	AUDITORIUM 303	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030385	3RD	AUDITORIUM 303	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030386	3RD	STAGE 303A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01030387	3RD	STAGE 303A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030388	3RD	DRESSING ROOM 303D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030389	3RD	DRESSING ROOM 303C	PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
PULL STATION	01030390	3RD	OUTSIDE STORAGE 303E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030391	3RD	INDUS ART 303	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030392	3RD	INDUS ART 303	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030393	3RD	ART 304	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030394	3RD	ART 304	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030395	3RD	CORRIDOR AT JANITOR 307B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030396	3RD	CORRIDOR AT AUDITORIUM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030397	3RD	CORRIDOR AT JANITOR 307B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030398	3RD	CORRIDOR AT CR-13 BY STAIR 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030399	3RD	CORRIDOR AT ROOM 316	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	01030400	3RD	CORRIDOR AT ELEVATOR EL1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030401	3RD	CORRIDOR AT ROOM 332	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	01030402	3RD	ROOM 335	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	01030403	3RD	ELECTRIC/BOILER 300C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020080	1ST	MEETING ROOM 107	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020079	1ST	MECHANICAL ROOM 108	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020078	1ST	OFFICE 100A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020077	1ST	OFFICE 100B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020076	1ST	STORAGE 101A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020075	1ST	CONFERENCE ROOM 101	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020074	1ST	CLASSROOM 102	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	01020070	1ST	CLASSROOM 103	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
BATTERIES				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT PEARL RIVER HIGH SCHOOL
275 EAST CENTRAL AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION**



Date: **8-1-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
A/V TEST				YES [☒] NO [☐]
ELEVATOR RECALL				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
FAN SHUTDOWN				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
CENTRAL STATION				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PANEL STATUS			AS FOUND IN TROUBLE AT PHONE LINE 2 FAULT	

PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **8-2-16**
 Techs: **OV/PB**
 System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0001	1ST	CORRIDOR AT BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0002	1ST	CORRIDOR AT ROOM 130	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0003	1ST	SPECIAL EDUCATION 132	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0004	1ST	CORRIDOR AT ROOM 133	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0005	1ST	CORRIDOR AT ROOM 135	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0006	1ST	STAIR ST-2 AT ROOM 135	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0008	1ST	CORRIDOR AT ROOM 115	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0009	1ST	CORRIDOR AT ROOM 115	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0010	1ST	ELEVATOR MACHINE ROOM EL1A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0011	1ST	STAIR ST-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0012	1ST	CORRIDOR AT ROOM 110	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0013	1ST	CORRIDOR AT OFFICE 111	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0014	1ST	STAIR ST-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0015	1ST	CORRIDOR CENTER	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0016	1ST	CORRIDOR AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0018	1ST	STAIR ST-5 AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0019	1ST	CORRIDOR AT ROOM 127	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0020	1ST	CORRIDOR AT ROOM 124	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0021	1ST	CORRIDOR AT ROOM 122	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0022	1ST	CORRIDOR AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0023	1ST	CORRIDOR AT ROOM 120	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0036	1ST	CORRIDOR CR-2 ELEVATOR EL1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	1-0037	1ST	AIR HAND 116A SUPPLY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	1-0038	1ST	AIR HAND 116A RETURN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	1-0039	1ST	OFFICE 112C RETURN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0043	1ST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0044	1ST	AIR HANDLER 116A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0045	1ST	AIR HANDLER 116A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0046	1ST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0047	1ST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0048	1ST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0049	1ST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0050	1ST	STORAGE 134B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0051	1ST	STORAGE 134A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0052	1ST	STORAGE 135B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0053	1ST	STORAGE 135A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0054	1ST	STORAGE 131A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0022	1ST	STORAGE 109B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0056	1ST	OFFICE 112C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0057	1ST	STORAGE 112A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0058	1ST	JANITOR 122A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0059	1ST	STORAGE 126A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0060	1ST	STORAGE 119A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0061	1ST	STORAGE 119A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0062	1ST	STORAGE 118A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0064	1ST	STORAGE 120A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0065	1ST	STORAGE 120A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION	1-0126	1ST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0127	1ST	CORRIDOR AT BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0128	1ST	SPECIAL EDUCATION 132	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0129	1ST	TECHNICIAN ROOM 134	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0130	1ST	CORRIDOR AT ROOM 134	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	1-0131	1ST	STAIR ST-2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0132	1ST	CORRIDOR AT ROOM 113	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0133	1ST	CORRIDOR AT ROOM 128	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0134	1ST	CORRIDOR AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0135	1ST	CORRIDOR AT ROOM 118	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0136	1ST	CORRIDOR AT ROOM 120	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0137	1ST	STAGE 119	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	1-0152	1ST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	1-0153	1ST	BOILER ROOM 116	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0251	2ND	CORRIDOR CR-2 ELEVATOR EL1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0252	2ND	CORRIDOR AT CAFETERIA	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0253	2ND	CORRIDOR AT CAFETERIA	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0254	2ND	STAIR ST-2 AT ROOM 238	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	2-0256	2ND	CORRIDOR AT ROOM 236	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0257	2ND	CORRIDOR AT ROOM 234	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0258	2ND	CORRIDOR AT ROOM 232	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0260	2ND	FACULTY DINING 213B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0261	2ND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0262	2ND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0263	2ND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0264	2ND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0265	2ND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0266	2ND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0267	2ND	CORRIDOR AT COPY ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0268	2ND	CORRIDOR AT OFFICE 205C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0269	2ND	MAIN OFFICE 205	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	2-0270	2ND	COPY ROOM 205A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0271	2ND	CORRIDOR AT OFFICE 210	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0272	2ND	LIBRARY 211	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0273	2ND	LIBRARY 211	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0274	2ND	LIBRARY 211	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0275	2ND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0276	2ND	CORRIDOR AT PSYCHOLOGIST	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0277	2ND	CORRIDOR AT MAIN OFFICE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0278	2ND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0279	2ND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0280	2ND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0281	2ND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0282	2ND	CORRIDOR AT NURSE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	2-0283	2ND	CORRIDOR AT TEACHER PREP	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0285	2ND	STAIR ST-5 AT ROOM 228	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0286	2ND	CORRIDOR AT ROOM 227	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0287	2ND	CORRIDOR AT ROOM 225	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0288	2ND	CORRIDOR AT ROOM 223	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0289	2ND	CORRIDOR AT ROOM 218	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0290	2ND	CORRIDOR AT ROOM 220	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0291	2ND	CORRIDOR AT ROOM 219	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0292	2ND	CORRIDOR AT ROOM 219	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0293	2ND	CORRIDOR LINK TO GYM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0294	2ND	CORRIDOR AT GIRLS LOCKER	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0295	2ND	GIRLS LOCKER ROOM 201G	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0296	2ND	GIRLS LOCKER ROOM 201G	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	2-0297	2ND	CORRIDOR AT BOYS LOCKER	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0298	2ND	STAIR ST-3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0299	2ND	BOYS LOCKER ROOM 201B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0300	2ND	BOYS LOCKER ROOM 201B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0301	2ND	CORRIDOR CR-6 ELEVATOR EL1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	2-0302	2ND	MECHANICAL ROOM 205B RETURN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	2-0303	2ND	MECHANICAL ROOM 205B SUPPLY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	2-0304	2ND	MECHANICAL ROOM 202 SUPPLY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	2-0305	2ND	MECHANICAL ROOM 202 RETURN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	2-0306	2ND	MECHANICAL ROOM 202 SUPPLY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	2-0307	2ND	MECHANICAL ROOM 202 SUPPLY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	2-0308	2ND	MECHANICAL ROOM 201M SUPPLY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	2-0309	2ND	MECHANICAL ROOM 201M RETURN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	2-0310	2ND	STORAGE 211A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0311	2ND	JANITOR 231A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0312	2ND	STORAGE 237A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0313	2ND	DRY STORAGE 213E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0314	2ND	KITCHEN 213A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0315	2ND	KITCHEN 213A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0316	2ND	CLOSET IN OFFICE 250C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0317	2ND	MECHANICAL ROOM 205B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0318	2ND	CLOSET IN LIBRARY 211	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0319	2ND	STORAGE 204	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0320	2ND	STORAGE 205F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0321	2ND	STORAGE 203E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0322	2ND	STORAGE 204A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	2-0323	2ND	JANITOR 222A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0324	2ND	STORAGE 226A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0325	2ND	MECHANICAL ROOM 202	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0326	2ND	MECHANICAL ROOM 202	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0327	2ND	STORAGE 202A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	2-0328	2ND	STORAGE 202A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	3-0329	2ND	P.E. OFFICE 201A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	3-0331	1ST	STAGE 119	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0332	1ST	STAGE 119	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0333	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0334	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0335	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0336	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	3-0337	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0338	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0339	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0340	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0341	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	3-0342	1ST	STAIR ST-3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	3-0343	1ST	STORAGE 120C RETURN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
DUCT DETECTOR	3-0344	1ST	STORAGE 120C SUPPLY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	3-0345	1ST	STORAGE 119B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	3-0346	1ST	STORAGE 120B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	3-0347	1ST	STORAGE 120C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION	3-0376	2ND	CORRIDOR AT ROOM 236	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0377	2ND	CORRIDOR AT ROOM 230	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	3-0378	2ND	KITCHEN 213A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0379	2ND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0380	2ND	CAFETERIA 213	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0381	2ND	CORRIDOR AT CAFETERIA	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0382	2ND	CORRIDOR AT MECHANICAL ROOM 205B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0383	2ND	CORRIDOR AT ROOM 212	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0384	2ND	CORRIDOR AT MAIN ENTRANCE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0385	2ND	AUDITORIUM 206	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0386	2ND	CORRIDOR AT ROOM 228	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0387	2ND	CORRIDOR AT ROOM 224	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0388	2ND	CORRIDOR AT ROOM 221	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0389	2ND	CORRIDOR AT GIRLS LOCKER	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0390	2ND	CORRIDOR AT BOYS LOCKER	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT
MIDDLE SCHOOL 520 GILBERT AVENUE PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-2-16**
Techs: **OV/PB**
System: **EST-3**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	3-0391	2ND	BOYS LOCKER ROOM 201B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0400	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0401	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0402	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0403	1ST	GYMNASIUM 201	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0404	1ST	WRESTLING ROOM 120B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	3-0405	1ST	STAIR ST-3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
BATTERIES				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
A/V TEST				YES [☒] NO [☐]
ELEVATOR RECALL				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
FAN SHUTDOWN				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
CENTRAL STATION				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PANEL STATUS			NORMAL	

**PEARL RIVER SCHOOL DISTRICT STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-3-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0001	1ST	CORRIDOR BY OFFICE 9A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0002	1ST	BY CLASSROOM 8B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0003	1ST	BY CLASSROOM 8B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0004	1ST	CORRIDOR BY CLASSROOM 8A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0005	1ST	LOBBY L-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0006	1ST	CORRIDOR BY OFFICE 8D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0007	1ST	CORRIDOR BY CLASSROOM 1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0008	1ST	CORRIDOR BY CLASSROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0009	1ST	CORRIDOR BY CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0010	1ST	CORRIDOR BY CLASSROOM 7	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0011	1ST	THERAPY 7A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0012	1ST	CLASSROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0013	1ST	CLASSROOM 5	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-3-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0014	1ST	CLASSROOM 4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0015	1ST	CLASSROOM 3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0016	1ST	CLASSROOM 2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0017	1ST	CLASSROOM 1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0018	1ST	LOBBY L-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0019	1ST	CORRIDOR BY CONFERENCE ROOM 10	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0020	1ST	CORRIDOR BY THERAPY 10B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0021	1ST	CORRIDOR BY OFFICE 17	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0022	1ST	CORRIDOR BY OFFICE 17B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0023	1ST	CORRIDOR BY GARAGE G-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0024	1ST	CORRIDOR BY GARAGE G-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0025	1ST	CORRIDOR BY JANITOR 20B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0026	1ST	CORRIDOR BY STORAGE 24	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-3-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
SMOKE DETECTOR	1-0027	1ST	CORRIDOR BY STORAGE 21	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0028	GROUND	BY TRANS OFFICE ENTRY	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	1-0029	1ST	CORRIDOR BY OFFICE 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0030	1ST	STORAGE ROOM 9E	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0031	1ST	MECHANICAL ROOM 9F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	1-0032	1ST	JANITOR CLOSET BY SHOP	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0033	1ST	STORAGE ROOM 10A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0034	1ST	STORAGE ROOM 22	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0035	1ST	CLOSET	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0036	1ST	STORAGE ROOM 24	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0037	1ST	STORAGE ROOM 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0038	1ST	STORAGE ROOM 21	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0039	1ST	WORK SHOP 20	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]

PEARL RIVER SCHOOL DISTRICT STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT



Date: **8-3-16**
 Techs: **OV/PB**
 System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
HEAT DETECTOR	1-0040	1ST	WORK SHOP 20	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0041	1ST	GARAGE G-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0042	1ST	GARAGE G-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0043	1ST	JANITOR CLOSET 20B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	1-0044	1ST	SMALL ARCHIVES STORAGE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR	1-0045	GROUND	STORAGE ROOM 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0046	GROUND	STORAGE ROOM 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0047	GROUND	BOILER ROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR	1-0048	1ST	STORAGE ROOM 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
SMOKE DETECTOR	1-0049	1ST	LARGE ARCHIVES STORAGE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0126	1ST	MECHANICAL ROOM 9F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0127	1ST	CORRIDOR BY OFFICE 9A	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0128	1ST	LOBBY L-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-3-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	1-0129	1ST	CORRIDOR BY OFFICE 8D	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0130	1ST	CORRIDOR BY CLASSROOM 7	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0131	1ST	CLASSROOM 1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0132	1ST	LOBBY L-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0133	1ST	VESTIBULE BY TOILET 10C	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0134	1ST	CORRIDOR BY GARAGE G-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0135	1ST	CORRIDOR BY JANITOR 20B	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0136	1ST	CORRIDOR BY STORAGE ROOM 24	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0137	1ST	CORRIDOR BY STORAGE ROOM 21	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0138	1ST	GARAGE G-1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0139	GROUND	CORRIDOR BY OFFICE 23	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	1-0140	GROUND	SHOP EXIT EAST	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
CO DETECTOR	1-0141	1ST	MECHANICAL ROOM 9F	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT STARTING PLACE & GARAGE BUILDING
664 ORANGEBURG ROAD PEARL RIVER, NY 10965
ANNUAL FIRE ALARM INSPECTION REPORT**

OPEN SYSTEMS
METRO

Date: **8-3-16**
Techs: **OV/PB**
System: EST-3

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
CO DETECTOR	1-0142	GROUND	BOILER ROOM 6	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
BATTERIES				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
A/V TEST				YES [☒] NO [☐]
ELEVATOR RECALL				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
FAN SHUTDOWN				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
CENTRAL STATION			44 CONTROL	PASS [☐] FAIL [☒] N/A [☐] VISUAL [☐]
PANEL STATUS			PHONE LINE FAILURE	

**PEARL RIVER SCHOOL DISTRICT WILLIAMS STREET ARC SCHOOL
37 FRANKLIN AVENUE PEARL RIVER, NY 10595
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **OV/PB**
System: **SILENT KNIGHT**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	004	1ST	VESTIBULE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	013	1ST	MAIN HALL #3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	010	1ST	MAIN HALL #2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	014	1ST	MAIN HALL #4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	007	1ST	MAIN HALL #1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	005	1ST	OFFICE HALLWAY #1	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	006	1ST	OFFICE HALLWAY #2	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	008	1ST	OFFICE HALLWAY #3	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
SMOKE DETECTOR	009	1ST	OFFICE HALLWAY #4	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
HEAT DETECTOR		1ST	KITCHEN	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
HEAT DETECTOR		1ST	BOILER ROOM	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☒]
PULL STATION	003	1ST	HALLWAY NORTH	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PULL STATION	002	1ST	HALLWAY MIDDLE	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]

**PEARL RIVER SCHOOL DISTRICT WILLIAMS STREET ARC SCHOOL
37 FRANKLIN AVENUE PEARL RIVER, NY 10595
ANNUAL FIRE ALARM INSPECTION REPORT**



Date: **8-4-16**
Techs: **OV/PB**
System: **SILENT KNIGHT**

DEVICE	ADDRESS	FLOOR	LOCATION	RESULTS
PULL STATION	001	1ST	HALLWAY SOUTH	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
BATTERIES				PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
A/V TEST				YES [☒] NO [☐]
ELEVATOR RECALL				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
FAN SHUTDOWN				PASS [☐] FAIL [☐] N/A [☒] VISUAL [☐]
CENTRAL STATION			44 CONTROL	PASS [☒] FAIL [☐] N/A [☐] VISUAL [☐]
PANEL STATUS			NORMAL	