



October 14, 2016

Adelaide Environmental Health
1511 Route 22, Suite C24
Brewster, NY 10509

Work Order No.: 16I1771

Re: Pearl River HS, 275 E. Central Ave, Pearl River NY

Dear John Soter:

Microbac Laboratories, Inc. - Chicagoland Division received 63 sample(s) on 9/28/2016 9:25:22AM for the analyses presented in the following report as Work Order 16I1771.

The enclosed results were obtained from and are applicable to the sample(s) as received at the laboratory. All sample results are reported on an "as received" basis unless otherwise noted.

All data included in this report have been reviewed and meet the applicable project specific and certification specific requirements, unless otherwise noted. A qualifications page is included in this report and lists the programs under which Microbac maintains certification.

This report has been paginated in its entirety and shall not be reproduced except in full, without the written approval of Microbac Laboratories.

We appreciate the opportunity to service your analytical needs. If you have any questions, please contact your project manager. For any feedback, please contact Robert Crookston, Managing Director, at robert.crookston@microbac.com.

Sincerely,
Microbac Laboratories, Inc.

A handwritten signature in black ink, appearing to read "Karen Ziolkowski", with a long horizontal line extending to the right.

Karen Ziolkowski
Senior Project Manager

[Microbac Laboratories, Inc.](http://www.microbac.com)

250 West 84th Drive | Merrillville, IN 46410 | 800.536.8379 p | 219.769.8378 p | 219.769.1664 f | www.microbac.com

**WORK ORDER SAMPLE SUMMARY****Date:**

Friday, October 14, 2016

Client: Adelaide Environmental Health
Project: Pearl River HS, 275 E. Central Ave, Pearl River NY
Lab Order: 1611771

Lab Sample ID	Client Sample ID	Tag Number	Collection Date	Date Received
1611771-01	16-117-PR-PRHS-BF-035	1ST Floor Gym Office	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-02	16-117-PR-PRHS-BF(A)-036	1ST Floor Gym Locker	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-03	16-117-PR-PRHS-BF(B)-037	1ST Floor Gym Locker	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-04	16-117-PR-PRHS-BF(C)-038	1ST Floor Gym Locker	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-05	16-117-PR-PRHS-BF(D)-039	1ST Floor Gym Locker	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-06	16-117-PR-PRHS-OT-40	1ST Floor Trainers Room	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-07	16-117-PR-PRHS-OT-41	1ST Floor Outside Trail	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-08	16-117-PR-PRHS-BF(A)-042	1ST Floor Girls Locker	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-09	16-117-PR-PRHS-BF(B)-043	1ST Floor Girls Locker	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-10	16-117-PR-PRHS-BF(C)-044	1ST Floor Girls Locker	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-11	16-117-PR-PRHS-BF(D)-045	1ST Floor Girls Locker	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-12	16-117-PR-PRHS-BF-046	1ST Floor Girls Coach	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-13	16-117-PR-PRHS-BF(A)-047	1st Floor Boys Bathroom	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-14	16-117-PR-PRHS-BF(B)-048	1st Floor Boys Bathroom	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-15	16-117-PR-PRHS-BF(C)-049	1st Floor Boys Bathroom	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-16	16-117-PR-PRHS-BF(A)-050	1st Floor Girls Bathroom	09/24/2016 00:00	9/29/2016 6:06:32PM
1611771-18	16-117-PR-PRHS-BF(C)-052	1st Floor Girls Bathroom	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-19	16-117-PR-PRHS-CF(A)-053	1ST Floor Room 104	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-20	16-117-PR-PRHS-CF(B)-054	1ST Floor Room 104	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-21	16-117-PR-PRHS-CF(C)-055	1ST Floor Room 104	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-22	16-117-PR-PRHS-OT-056	1ST Floor Room 104	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-23	16-117-PR-PRHS-TL-057	1ST Floor Faculty Lounge	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-24	16-117-PR-PRHS-KF-058	1ST Floor Kitchen	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-25	16-117-PR-PRHS-BF-059	1ST Floor Kitchen	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-26	16-117-PR-PRHS-BF(A)-060	1ST Floor Pirates Cove	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-27	16-117-PR-PRHS-BF(B)-061	1ST Floor Pirates Cove	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-28	16-117-PR-PRHS-BF(A)-062	1ST Floor Pirates Cove	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-29	16-117-PR-PRHS-BF(B)-063	1ST Floor Pirates Cove	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-30	16-117-PR-PRHS-KF-064	1ST Floor Pirates Cove	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-31	16-117-PR-PRHS-BF-065	1ST Floor Staff Bathroom	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-32	16-117-PR-PRHS-BF-066	1ST Floor Bathroom	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-33	16-117-PR-PRHS-CF(A)-067	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-34	16-117-PR-PRHS-CF(B)-068	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-35	16-117-PR-PRHS-CF(C)-069	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-36	16-117-PR-PRHS-CF(D)-070	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-37	16-117-PR-PRHS-CF(E)-071	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-38	16-117-PR-PRHS-CF(F)-072	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-39	16-117-PR-PRHS-CF(G)-073	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-40	16-117-PR-PRHS-CF(H)-074	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-41	16-117-PR-PRHS-CF(I)-075	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM
1611771-42	16-117-PR-PRHS-CF(J)-076	2ND Floor Room 220	09/24/2016 00:00	9/29/2016 6:06:33PM

Microbac Laboratories, Inc.

250 West 84th Drive | Merrillville, IN 46410 | 800.536.8379 p | 219.769.8378 p | 219.769.1664 f | www.microbac.com

**WORK ORDER SAMPLE SUMMARY****Date:***Friday, October 14, 2016*

1611771-43	16-117-PR-PRHS-CF(K)-077	2ND Floor Room 220 L09/24/2016 00:00	9/29/2016	6:06:33PM
1611771-44	16-117-PR-PRHS-CF(L)-078	2ND Floor Room 220 L09/24/2016 00:00	9/29/2016	6:06:33PM
1611771-45	16-117-PR-PRHS-CF(M)-079	2ND Floor Room 220 L09/24/2016 00:00	9/29/2016	6:06:33PM
1611771-46	16-117-PR-PRHS-CF(N)-080	2ND Floor Room 220 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-47	16-117-PR-PRHS-CF(A)-081	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-48	16-117-PR-PRHS-CF(B)-082	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-49	16-117-PR-PRHS-CF(C)-083	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-50	16-117-PR-PRHS-CF(D)-084	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-51	16-117-PR-PRHS-CF(E)-085	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-52	16-117-PR-PRHS-CF(F)-086	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-53	16-117-PR-PRHS-CF(G)-087	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-54	16-117-PR-PRHS-CF(H)-088	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-55	16-117-PR-PRHS-CF(I)-089	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-56	16-117-PR-PRHS-CF(J)-090	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-57	16-117-PR-PRHS-CF(K)-091	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-58	16-117-PR-PRHS-CF(L)-092	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-59	16-117-PR-PRHS-CF(M)-093	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-60	16-117-PR-PRHS-CF(N)-094	2ND Floor Room 224 L09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-61	16-117-PR-PRHS-OT-095	1ST Floor Girls Locker 09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-62	16-117-PR-PRHS-OT-096	1ST Floor Boys Locker 09/24/2016 00:00	9/29/2016	6:06:34PM
1611771-63	16-117-PR-PRHS-OT-097	1ST Floor Training Room 09/24/2016 00:00	9/29/2016	6:06:34PM

[Microbac Laboratories, Inc.](#)250 West 84th Drive | Merrillville, IN 46410 | 800.536.8379 p | 219.769.8378 p | 219.769.1664 f | www.microbac.com

Analytical Results

Date: Friday, October 14, 2016

Client: Adelaide Environmental Health
Client Project: Pearl River HS, 275 E. Central Ave, Pearl River NY
Work Order: 1611771
Received: 09/29/2016 18:06

Analyses	Certs	Result	Units	Qual	Analyzed	Tech	Method
01 16-117-PR-PRHS-BF-035 - 1ST Floor Gym Office Boys Single Sink							Collected: 09/24/2016 00:00
Lead	gdmnoi	5.5	ug/L		10/10/2016 17:48	RPL	EPA 200.8 Rev 5.4
02 16-117-PR-PRHS-BF(A)-036 - 1ST Floor Gym Locker Room Boys Sink A Right							Collected: 09/24/2016 00:00
Lead	gdmnoi	< 5.0	ug/L		10/10/2016 17:50	RPL	EPA 200.8 Rev 5.4
03 16-117-PR-PRHS-BF(B)-037 - 1ST Floor Gym Locker Room Boys Sink B Right Center							Collected: 09/24/2016 00:00
Lead	gdmnoi	< 5.0	ug/L		10/10/2016 17:51	RPL	EPA 200.8 Rev 5.4
04 16-117-PR-PRHS-BF(C)-038 - 1ST Floor Gym Locker Room Boys Sink C Left Center							Collected: 09/24/2016 00:00
Lead	gdmnoi	< 5.0	ug/L		10/10/2016 17:52	RPL	EPA 200.8 Rev 5.4
05 16-117-PR-PRHS-BF(D)-039 - 1ST Floor Gym Locker Room Boys Sink D Left							Collected: 09/24/2016 00:00
Lead	gdmnoi	< 5.0	ug/L		10/10/2016 17:53	RPL	EPA 200.8 Rev 5.4
06 16-117-PR-PRHS-OT-40 - 1ST Floor Trainers Room Single Sink							Collected: 09/24/2016 00:00
Lead	gdmnoi	< 5.0	ug/L		10/10/2016 17:55	RPL	EPA 200.8 Rev 5.4
07 16-117-PR-PRHS-OT-41 - 1ST Floor Outside Trainers Room Hose Bib							Collected: 09/24/2016 00:00
Lead	gdmnoi	6.8	ug/L		10/10/2016 17:56	RPL	EPA 200.8 Rev 5.4
08 16-117-PR-PRHS-BF(A)-042 - 1ST Floor Girls Locker Room Left Side Sink A Left							Collected: 09/24/2016 00:00
Lead	gdmnoi	8.6	ug/L		10/10/2016 17:57	RPL	EPA 200.8 Rev 5.4
09 16-117-PR-PRHS-BF(B)-043 - 1ST Floor Girls Locker Room Left Side Sink B Right							Collected: 09/24/2016 00:00
Lead	gdmnoi	7.5	ug/L		10/10/2016 17:58	RPL	EPA 200.8 Rev 5.4
10 16-117-PR-PRHS-BF(C)-044 - 1ST Floor Girls Locker Room Right Side Sink C Right							Collected: 09/24/2016 00:00
Lead	gdmnoi	7.2	ug/L		10/10/2016 18:00	RPL	EPA 200.8 Rev 5.4

Microbac Laboratories, Inc.

250 West 84th Drive | Merrillville, IN 46410 | 800.536.8379 p | 219.769.8378 p | 219.769.1664 f | www.microbac.com

Analytical Results

Date: Friday, October 14, 2016

11 16-117-PR-PRHS-BF(D)-045 - 1ST Floor Girls Locker Room Right Side Sink D Left Collected: 09/24/2016 00:00

Lead gdmnoi 7.9 ug/L 10/10/2016 18:01 RPL EPA 200.8 Rev 5.4

12 16-117-PR-PRHS-BF-046 - 1ST Floor Girls Coaches Office Single Sink Collected: 09/24/2016 00:00

Lead gdmnoi 11 ug/L 10/10/2016 18:02 RPL EPA 200.8 Rev 5.4

13 16-117-PR-PRHS-BF(A)-047 - 1st Floor Boys Bathroom Gym Entrance Sink A Right Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:02 RPL EPA 200.8 Rev 5.4

14 16-117-PR-PRHS-BF(B)-048 - 1st Floor Boys Bathroom Gym Entrance Sink B Center Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:03 RPL EPA 200.8 Rev 5.4

15 16-117-PR-PRHS-BF(C)-049 - 1st Floor Boys Bathroom Gym Entrance Sink C Left Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:04 RPL EPA 200.8 Rev 5.4

16 16-117-PR-PRHS-BF(A)-050 - 1st Floor Girls Bathroom Gym Entrance Sink A Left Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:06 RPL EPA 200.8 Rev 5.4

18 16-117-PR-PRHS-BF(C)-052 - 1st Floor Girls Bathroom Gym Entrance Sink C Right Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:07 RPL EPA 200.8 Rev 5.4

19 16-117-PR-PRHS-CF(A)-053 - 1ST Floor Room 104 West Wall Sink A Right Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:10 RPL EPA 200.8 Rev 5.4

20 16-117-PR-PRHS-CF(B)-054 - 1ST Floor Room 104 West Wall Sink B Left Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:11 RPL EPA 200.8 Rev 5.4

21 16-117-PR-PRHS-CF(C)-055 - 1ST Floor Room 104 East Wall Sink C Single Sink Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:11 RPL EPA 200.8 Rev 5.4

22 16-117-PR-PRHS-OT-056 - 1ST Floor Room 104 Outside Hose Bib Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:12 RPL EPA 200.8 Rev 5.4

Microbac Laboratories, Inc.

250 West 84th Drive | Merrillville, IN 46410 | 800.536.8379 p | 219.769.8378 p | 219.769.1664 f | www.microbac.com

Analytical Results

Date: Friday, October 14, 2016

23 16-117-PR-PRHS-TL-057 - 1ST Floor Faculty Lounge Kitchen Sink Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:13 RPL EPA 200.8 Rev 5.4

24 16-117-PR-PRHS-KF-058 - 1ST Floor Kitchen Steamer right near Window Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:14 RPL EPA 200.8 Rev 5.4

25 16-117-PR-PRHS-BF-059 - 1ST Floor Kitchen Bathroom Single Sink Collected: 09/24/2016 00:00

Lead gdmnoi 5.7 ug/L 10/10/2016 18:15 RPL EPA 200.8 Rev 5.4

26 16-117-PR-PRHS-BF(A)-060 - 1ST Floor Pirates Cove Girls Bathroom Sink A Right Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:17 RPL EPA 200.8 Rev 5.4

27 16-117-PR-PRHS-BF(B)-061 - 1ST Floor Pirates Cove Girls Bathroom Sink B Left Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:19 RPL EPA 200.8 Rev 5.4

28 16-117-PR-PRHS-BF(A)-062 - 1ST Floor Pirates Cove Boys Bathroom Sink A Left Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:20 RPL EPA 200.8 Rev 5.4

29 16-117-PR-PRHS-BF(B)-063 - 1ST Floor Pirates Cove Boys Bathroom Sink B Right Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:21 RPL EPA 200.8 Rev 5.4

30 16-117-PR-PRHS-KF-064 - 1ST Floor Pirates Cove Kitchenette Single Sink Collected: 09/24/2016 00:00

Lead dgimno 12 ug/L 10/12/2016 17:27 SJE EPA 200.8 Rev 5.4

31 16-117-PR-PRHS-BF-065 - 1ST Floor Staff Bathroom Near Rm 108A Single Sink Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:22 RPL EPA 200.8 Rev 5.4

32 16-117-PR-PRHS-BF-066 - 1ST Floor Bathroom Near Rm 109 Single Sink Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 18:23 RPL EPA 200.8 Rev 5.4

33 16-117-PR-PRHS-CF(A)-067 - 2ND Floor Room 220 Lab Sink A Table at Door 1 Collected: 09/24/2016 00:00

Lead gdmnoi 14 ug/L 10/10/2016 18:23 RPL EPA 200.8 Rev 5.4

Microbac Laboratories, Inc.

250 West 84th Drive | Merrillville, IN 46410 | 800.536.8379 p | 219.769.8378 p | 219.769.1664 f | www.microbac.com

Analytical Results

Date: Friday, October 14, 2016

34 16-117-PR-PRHS-CF(B)-068 - 2ND Floor Room 220 Lab Sink B Table at Door 1 Collected: 09/24/2016 00:00

Lead gdmnoi 46 ug/L 10/10/2016 18:24 RPL EPA 200.8 Rev 5.4

35 16-117-PR-PRHS-CF(C)-069 - 2ND Floor Room 220 Lab Sink C Table 2 Collected: 09/24/2016 00:00

Lead gdmnoi 8.0 ug/L 10/10/2016 18:25 RPL EPA 200.8 Rev 5.4

36 16-117-PR-PRHS-CF(D)-070 - 2ND Floor Room 220 Lab Sink D Table 2 Collected: 09/24/2016 00:00

Lead gdmnoi 9.8 ug/L 10/10/2016 18:29 RPL EPA 200.8 Rev 5.4

37 16-117-PR-PRHS-CF(E)-071 - 2ND Floor Room 220 Lab Sink E Table 3 Collected: 09/24/2016 00:00

Lead gdmnoi 8.1 ug/L 10/10/2016 18:30 RPL EPA 200.8 Rev 5.4

38 16-117-PR-PRHS-CF(F)-072 - 2ND Floor Room 220 Lab Sink F Table 3 Collected: 09/24/2016 00:00

Lead gdmnoi 6.3 ug/L 10/10/2016 18:31 RPL EPA 200.8 Rev 5.4

39 16-117-PR-PRHS-CF(G)-073 - 2ND Floor Room 220 Lab Sink G Table 4 Collected: 09/24/2016 00:00

Lead gdmnoi 33 ug/L 10/10/2016 18:32 RPL EPA 200.8 Rev 5.4

40 16-117-PR-PRHS-CF(H)-074 - 2ND Floor Room 220 Lab Sink H Table 4 Collected: 09/24/2016 00:00

Lead gdmnoi 6.3 ug/L 10/10/2016 18:32 RPL EPA 200.8 Rev 5.4

41 16-117-PR-PRHS-CF(I)-075 - 2ND Floor Room 220 Lab Sink I Table 5 Collected: 09/24/2016 00:00

Lead gdmnoi 23 ug/L 10/10/2016 18:33 RPL EPA 200.8 Rev 5.4

42 16-117-PR-PRHS-CF(J)-076 - 2ND Floor Room 220 Lab Sink J Table 5 Collected: 09/24/2016 00:00

Lead gdmnoi 15 ug/L 10/10/2016 18:34 RPL EPA 200.8 Rev 5.4

43 16-117-PR-PRHS-CF(K)-077 - 2ND Floor Room 220 Lab Sink K Table 6 Collected: 09/24/2016 00:00

Lead gdmnoi 57 ug/L 10/10/2016 18:35 RPL EPA 200.8 Rev 5.4

44 16-117-PR-PRHS-CF(L)-078 - 2ND Floor Room 220 Lab Sink L Table 6 Collected: 09/24/2016 00:00

Lead gdmnoi 88 ug/L 10/10/2016 18:36 RPL EPA 200.8 Rev 5.4

Microbac Laboratories, Inc.

250 West 84th Drive | Merrillville, IN 46410 | 800.536.8379 p | 219.769.8378 p | 219.769.1664 f | www.microbac.com

Analytical Results

Date: Friday, October 14, 2016

45 16-117-PR-PRHS-CF(M)-079 - 2ND Floor Room 220 Lab Sink M Teachers Table Collected: 09/24/2016 00:00

Lead gdmnoi 15 ug/L 10/10/2016 18:38 RPL EPA 200.8 Rev 5.4

46 16-117-PR-PRHS-CF(N)-080 - 2ND Floor Room 220 Lab Sink N Back Wall Collected: 09/24/2016 00:00

Lead gdmnoi 35 ug/L 10/10/2016 18:42 RPL EPA 200.8 Rev 5.4

47 16-117-PR-PRHS-CF(A)-081 - 2ND Floor Room 224 Lab Sink A Table at Door 1 Collected: 09/24/2016 00:00

Lead gdmnoi 12 ug/L 10/10/2016 18:42 RPL EPA 200.8 Rev 5.4

48 16-117-PR-PRHS-CF(B)-082 - 2ND Floor Room 224 Lab Sink B Table at Door 1 Collected: 09/24/2016 00:00

Lead gdmnoi 10 ug/L 10/10/2016 18:43 RPL EPA 200.8 Rev 5.4

49 16-117-PR-PRHS-CF(C)-083 - 2ND Floor Room 224 Lab Sink C Table 2 Collected: 09/24/2016 00:00

Lead gdmnoi 16 ug/L 10/10/2016 18:44 RPL EPA 200.8 Rev 5.4

50 16-117-PR-PRHS-CF(D)-084 - 2ND Floor Room 224 Lab Sink D Table 2 Collected: 09/24/2016 00:00

Lead gdmnoi 21 ug/L 10/10/2016 18:45 RPL EPA 200.8 Rev 5.4

51 16-117-PR-PRHS-CF(E)-085 - 2ND Floor Room 224 Lab Sink E Table 3 Collected: 09/24/2016 00:00

Lead gdmnoi 240 ug/L E 10/10/2016 18:46 RPL EPA 200.8 Rev 5.4

52 16-117-PR-PRHS-CF(F)-086 - 2ND Floor Room 224 Lab Sink F Table 3 Collected: 09/24/2016 00:00

Lead gdmnoi 670 ug/L E 10/10/2016 18:46 RPL EPA 200.8 Rev 5.4

53 16-117-PR-PRHS-CF(G)-087 - 2ND Floor Room 224 Lab Sink G Table 4 Collected: 09/24/2016 00:00

Lead gdmnoi 44 ug/L 10/10/2016 18:48 RPL EPA 200.8 Rev 5.4

54 16-117-PR-PRHS-CF(H)-088 - 2ND Floor Room 224 Lab Sink H Table 4 Collected: 09/24/2016 00:00

Lead gdmnoi 190 ug/L E 10/10/2016 18:51 RPL EPA 200.8 Rev 5.4

55 16-117-PR-PRHS-CF(I)-089 - 2ND Floor Room 224 Lab Sink I Table 5 Collected: 09/24/2016 00:00

Lead gdmnoi 180 ug/L E 10/10/2016 18:53 RPL EPA 200.8 Rev 5.4

Microbac Laboratories, Inc.

250 West 84th Drive | Merrillville, IN 46410 | 800.536.8379 p | 219.769.8378 p | 219.769.1664 f | www.microbac.com

Analytical Results

Date: Friday, October 14, 2016

56 16-117-PR-PRHS-CF(J)-090 - 2ND Floor Room 224 Lab Sink J Table 5 Collected: 09/24/2016 00:00

Lead dgimnoi 630 ug/L E 10/12/2016 17:31 SJE EPA 200.8 Rev 5.4

57 16-117-PR-PRHS-CF(K)-091 - 2ND Floor Room 224 Lab Sink K Table 6 Collected: 09/24/2016 00:00

Lead gdmnoi 12 ug/L 10/10/2016 18:58 RPL EPA 200.8 Rev 5.4

58 16-117-PR-PRHS-CF(L)-092 - 2ND Floor Room 224 Lab Sink L Table 6 Collected: 09/24/2016 00:00

Lead gdmnoi 62 ug/L 10/10/2016 18:59 RPL EPA 200.8 Rev 5.4

59 16-117-PR-PRHS-CF(M)-093 - 2ND Floor Room 224 Lab Sink M Teachers Table Collected: 09/24/2016 00:00

Lead gdmnoi 24 ug/L 10/10/2016 19:00 RPL EPA 200.8 Rev 5.4

60 16-117-PR-PRHS-CF(N)-094 - 2ND Floor Room 224 Lab Sink N Back Wall Collected: 09/24/2016 00:00

Lead gdmnoi 11 ug/L 10/10/2016 19:01 RPL EPA 200.8 Rev 5.4

61 16-117-PR-PRHS-OT-095 - 1ST Floor Girls Locker Room Ice Machine Collected: 09/24/2016 00:00

Lead gdmnoi 14 ug/L 10/10/2016 19:02 RPL EPA 200.8 Rev 5.4

62 16-117-PR-PRHS-OT-096 - 1ST Floor Boys Locker Room Ice Machine Collected: 09/24/2016 00:00

Lead gdmnoi < 5.0 ug/L 10/10/2016 19:02 RPL EPA 200.8 Rev 5.4

63 16-117-PR-PRHS-OT-097 - 1ST Floor Training Room Ice Machine Collected: 09/24/2016 00:00

Lead gdmnoi 9.0 ug/L 10/10/2016 19:05 RPL EPA 200.8 Rev 5.4

FLAGS, FOOTNOTES AND ABBREVIATIONS (as needed)

B = Detected in the associated method Blank at a concentration above the routine RL
 b- = Detected in the associated method Blank at a concentration greater than 2.2 times the MDL
 b* = Detected in the associated method Blank at a concentration greater than half the RL
 CFU = Colony forming units
 D = Dilution performed on sample
 DF = Dilution Factor
 g = Gram
 E = Value above quantitation range
 H = Analyte was prepared and/or analyzed outside of the analytical method holding time
 I = Matrix Interference
 J = Analyte concentration detected between RL and MDL (Metals / Organics)
 LOD = Limit of Detection
 LOQ = Limit of Quantitation
 m3 = Meters cubed
 MDL = Method Detection Limit
 mg/Kg = Milligrams per Kilogram (ppm)
 mg/L = Milligrams per Liter (ppm)
 NA = Not Analyzed
 ND = Not Detected at the Reporting Limit (or the Method Detection Limit, if used)
 NR = Not Recovered
 R = RPD outside accepted recovery limits
 RL = Reporting Limit
 S = Spike recovery outside recovery limits
 Surr = Surrogate
 U = Undetected
 > = Greater than
 < = Less than
 % = Percent
 * = Result exceeds project specific limits

ANALYTE TYPES: (AT)

A,B = Target Analyte
 I = Internal Standard
 M = Summation Analyte
 S = Surrogate
 T = Tentatively Identified Compound (TIC, concentration estimated)

QC SAMPLE IDENTIFICATIONS

BLK = Method Blank	ICSA = Interference Check Standard "A"
DUP = Method Duplicate	ICSAB = Interference Check Standard "AB"
BS = Method Blank Spike	BSD = Method Blank Spike Duplicate
MS = Matrix Spike	MSD = Matrix Spike Duplicate
ICB = Initial Calibration Blank	ICV = Initial Calibration Verification
CCB = Continuing Calibration Blank	CCV = Continuing Calibration Verification
CRL = Client Required Reporting Limit	OPR = Ongoing Precision and Recovery Standard
PDS = Post Digestion Spike	SD = Serial Dilution
QCS = Quality Control Standard	

CERTIFICATIONS (Certs)

Below is a list of certifications maintained by the Microbac Merrillville Laboratory. All data included in this report has been reviewed for and meets all project specific and quality control requirements of the applicable accreditation, unless otherwise noted. Complete lists of individual analytes pursuant to each certification below are available upon request.

- ^d Illinois EPA drinking water, wastewater and solid waste analysis (#200064)
- ^g Indiana SDH chemical analysis of drinking water (#C-45-03)
- ⁱ Kansas Dept Health & Env. NELAP (#E-10397)
- ^m New York State Department of Health Wadsworth (#12006)
- ⁿ Pennsylvania Department of Environmental Protection (#68-04863)
- ^o Virginia Department of General Services Division of Consolidated Laboratory Services (#7990)



COOLER INSPECTION

Client Name: Adelaide Environmental Health

Work Order Number: 1611771

Checklist completed by: 9/29/2016 6:06:31PM | Nicole Rainwater

Carrier Name: UPS

Date: Friday, October 14, 2016

Date/Time Received: 09/28/2016 09:25

Received by: Nicole Rainwater

Reviewed by: 10/5/2016 | KAZ

Cooler ID: Default Cooler

Container/Temp Blank Temperature: 21.4° C

After-Hour Arrival?	Yes	☐	No	☒	
Shipping container/cooler in good condition?	Yes	☒	No	☐	Not Present ☐
Custody seals intact on shipping container/cooler?	Yes	☐	No	☐	Not Present ☒
Custody seals intact on sample containers?	Yes	☐	No	☐	Not Present ☒
COC present?	Yes	☒	No	☐	
COC included sufficient client identification?	Yes	☒	No	☐	
COC included sufficient sample collector information?	Yes	☒	No	☐	
COC included a sample description?	Yes	☒	No	☐	
COC agrees with sample labels?	Yes	☒	No	☐	
COC identified the appropriate matrix?	Yes	☒	No	☐	
COC included date of collection?	Yes	☒	No	☐	
COC included time of collection?	Yes	☒	No	☐	
COC identified the appropriate number of containers?	Yes	☒	No	☐	
Samples in proper container/bottle?	Yes	☒	No	☐	
Sample containers intact?	Yes	☒	No	☐	
Sufficient sample volume for indicated test?	Yes	☒	No	☐	
All samples received within holding time?	Yes	☒	No	☐	
If the samples are preserved, are the preservatives identified?	Yes	☒	No	☐	

If No, adjusted by? _____

COC included the requested analyses?	Yes	☒	No	☐	
COC signed when relinquished and received?	Yes	☒	No	☐	
Samples received on ice?	Yes	☐	No	☒	
Samples properly preserved?	Yes	☒	No	☐	
Voa vials for aqueous samples have zero headspace?	Yes	☐	No	☐	No VOA vials submitted ☒

Cooler Comments: _____

ANY "NO" EVALUATION (excluding After-Hour Receipt) REQUIRES CLIENT NOTIFICATION.

Microbac Laboratories, Inc.

250 West 84th Drive | Merrillville, IN 46410 | 800.536.8379 p | 219.769.8378 p | 219.769.1664 f | www.microbac.com

Sample ID	Client Sample ID	Comments
16I1771-01	16-117-PR-PRHS-BF-035	
16I1771-02	16-117-PR-PRHS-BF(A)-036	
16I1771-03	16-117-PR-PRHS-BF(B)-037	
16I1771-04	16-117-PR-PRHS-BF(C)-038	
16I1771-05	16-117-PR-PRHS-BF(D)-039	
16I1771-06	16-117-PR-PRHS-OT-40	
16I1771-07	16-117-PR-PRHS-OT-41	
16I1771-08	16-117-PR-PRHS-BF(A)-042	
16I1771-09	16-117-PR-PRHS-BF(B)-043	
16I1771-10	16-117-PR-PRHS-BF(C)-044	
16I1771-11	16-117-PR-PRHS-BF(D)-045	
16I1771-12	16-117-PR-PRHS-BF-046	
16I1771-13	16-117-PR-PRHS-BF(A)-047	
16I1771-14	16-117-PR-PRHS-BF(B)-048	
16I1771-15	16-117-PR-PRHS-BF(C)-049	
16I1771-16	16-117-PR-PRHS-BF(A)-050	
16I1771-17	16-117-PR-PRHS-BF(B)-051	
16I1771-18	16-117-PR-PRHS-BF(C)-052	
16I1771-19	16-117-PR-PRHS-CF(A)-053	
16I1771-20	16-117-PR-PRHS-CF(B)-054	
16I1771-21	16-117-PR-PRHS-CF(C)-055	
16I1771-22	16-117-PR-PRHS-OT-056	
16I1771-23	16-117-PR-PRHS-TL-057	
16I1771-24	16-117-PR-PRHS-KF-058	
16I1771-25	16-117-PR-PRHS-BF-059	
16I1771-26	16-117-PR-PRHS-BF(A)-060	
16I1771-27	16-117-PR-PRHS-BF(B)-061	
16I1771-28	16-117-PR-PRHS-BF(A)-062	
16I1771-29	16-117-PR-PRHS-BF(B)-063	
16I1771-30	16-117-PR-PRHS-KF-064	
16I1771-31	16-117-PR-PRHS-BF-065	
16I1771-32	16-117-PR-PRHS-BF-066	
16I1771-33	16-117-PR-PRHS-CF(A)-067	
16I1771-34	16-117-PR-PRHS-CF(B)-068	
16I1771-35	16-117-PR-PRHS-CF(C)-069	
16I1771-36	16-117-PR-PRHS-CF(D)-070	
16I1771-41	16-117-PR-PRHS-CF(I)-075	
16I1771-42	16-117-PR-PRHS-CF(J)-076	
16I1771-43	16-117-PR-PRHS-CF(K)-077	
16I1771-44	16-117-PR-PRHS-CF(L)-078	
16I1771-49	16-117-PR-PRHS-CF(C)-083	
16I1771-50	16-117-PR-PRHS-CF(D)-084	
16I1771-51	16-117-PR-PRHS-CF(E)-085	
16I1771-52	16-117-PR-PRHS-CF(F)-086	
16I1771-57	16-117-PR-PRHS-CF(K)-091	
16I1771-58	16-117-PR-PRHS-CF(L)-092	
16I1771-59	16-117-PR-PRHS-CF(M)-093	
16I1771-60	16-117-PR-PRHS-CF(N)-094	
16I1771-37	16-117-PR-PRHS-CF(E)-071	

Microbac Laboratories, Inc.

16I1771-38	16-117-PR-PRHS-CF(F)-072
16I1771-39	16-117-PR-PRHS-CF(G)-073
16I1771-40	16-117-PR-PRHS-CF(H)-074
16I1771-45	16-117-PR-PRHS-CF(M)-079
16I1771-46	16-117-PR-PRHS-CF(N)-080
16I1771-47	16-117-PR-PRHS-CF(A)-081
16I1771-48	16-117-PR-PRHS-CF(B)-082
16I1771-53	16-117-PR-PRHS-CF(G)-087
16I1771-54	16-117-PR-PRHS-CF(H)-088
16I1771-55	16-117-PR-PRHS-CF(I)-089
16I1771-56	16-117-PR-PRHS-CF(J)-090
16I1771-61	16-117-PR-PRHS-OT-095
16I1771-62	16-117-PR-PRHS-OT-096
16I1771-63	16-117-PR-PRHS-OT-097

Adelaide Environmental
1511 Rt 22, Suite C24
Brewster, NY 10509
adelaidelabresults@adelaidellc.com

Field Chain-of-Custody Record

Lead in Drinking Water

Turn around time: Standard

Adelaide Project # BOCE:16250.05-WA

Pearl River High School
275 East Central Avenue
Pearl River, NY 10965

Site:

1611771
Adelaide Environmental Health - Brewster NY
DW Lead
09/29/2016

Karen Ziolkowski

Sample ID	Floor #	Sample Description	Analysis	Matrix	Container
R-PRHS- BF - 035	1	Gym Office Boys single Sink	Lead	Drinking Water	250 ml Bottle
R-PRHS- BF(A) - 036	1	Gym Office Room Boys SINK A Right	Lead	Drinking Water	250 ml Bottle
R-PRHS- BF(B) - 037	1	B Right Center	Lead	Drinking Water	250 ml Bottle
R-PRHS- BF(C) - 038	1	C Left Center	Lead	Drinking Water	250 ml Bottle
R-PRHS- BF(D) - 039	1	D Left	Lead	Drinking Water	250 ml Bottle
R-PRHS- OT - 040	1	Trainer's Room single Sink	Lead	Drinking Water	250 ml Bottle
R-PRHS- OT - 041	1	outside Trainer Room Hose Bib	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BA(A) - 042	1	Girls Locker Room Left side sink A Left	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(B) - 043	1	B V B Right	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(C) - 044	1	Right side sink C Right	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(D) - 045	1	V V D Left	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF - 046	1	Girls Coaches Office single Sink	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(Q) - 047	1	Boys Bathroom gym Entrance sink A Right	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(B) - 048	1	sink B center	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(C) - 049	1	sink C Left	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(A) - 050		Girls Bathroom gym Entrance sink A Left	Lead	Drinking Water	250 ml Bottle

Samples taken by:

Robert Sae 9-24-16
Signature / Date

Samples relinquished by:

Robert Sae 9-24-16
Signature / Date

Samples received by:

Nicole Rana 9-28-16
Signature / Date

Adelaide Environmental
1511 Rt 22, Suite C24
Brewster, NY 10509
adelaide@labresults.com

Field Chain-of-Custody Record

Lead in Drinking Water

Turn around time: Standard

Adelaide Project # BOCE:16250.05-WA

Site: Pearl River High School
275 East Central Avenue
Pearl River, NY 10965

District: Pearl River

Lab Project Number:

Date: 9-24-16

Inspector: Robert Se...

Page 2 of 4

Sample ID	Floor #	Sample Description	Analysis	Matrix	Container
16-117-PR-PRHS- BF(B) - 051	1	Girls Bathroom Not Submitted	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(B) - 052	1	Girls Bathroom Gym Entrance Sink C Right	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(A) - 053	1	Room 104 West Wall Sink B Right	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(B) - 054	1	Sink B Left	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(C) - 055	1	Fresh Wall Sink C Single Sink	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- OT - 056	1	outside hose Bib	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- TL - 057	1	Faculty Lounge kitchen sink	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- KF - 058	1	Kitchen Steamer Right Near Wall	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF - 059	1	Kitchen Bathroom single sink	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(A) - 060	1	Pinkies Care Girls Bathroom Sink A Right	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(B) - 061	1	V Sink B Left	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(A) - 062	1	Boys Sink A Left	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF(B) - 063	1	Boys Sink B Right	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- KF - 064	1	Kitchen Sink single sink	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF - 065	1	Staff Bathroom near RM 108A single sink	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- BF - 066	1	Bath room near Room 109 single sink	Lead	Drinking Water	250 ml Bottle

Samples taken by:

Robert Se... 9-24-16
Signature / Date

Samples relinquished by:

Robert Se... 9-24-16
Signature / Date

Samples received by:

Adelaide Environmental
9-28-16
0435
Signature / Date

Adelaide Environmental
1511 Rt 22, Suite C24
Brewster, NY 10509
adelaide@results@adelaideinc.com

Field Chain-of-Custody Record

Lead in Drinking Water

Turn around time: Standard

Adelaide Project # BOCE:16250.05-WA

Site:
Pearl River High School
275 East Central Avenue
Pearl River, NY 10965

District: Pearl River

Page 3 of 4

Lab Project Number:

Date: 9-24-16

Inspector: Robert See

Sample ID	Floor #	Sample Description	Analysis	Matrix	Container
16-117-PR-PRHS- CF(A) - 067	2	Room 220 Lab Sink A	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(B) - 068		B	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(C) - 069		C	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(D) - 070		D	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(E) - 071		E	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(F) - 072		F	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(G) - 073		G	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(H) - 074		H	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(I) - 075		I	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(J) - 076		J	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(K) - 077		K	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(L) - 078		L	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(M) - 079		M	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(N) - 080		N	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(A) - 081		Room 220 A	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF(B) - 082		B	Lead	Drinking Water	250 ml Bottle

Samples taken by:

Robert See 9-24-16

Signature / Date

Samples relinquished by:

Robert See 9-24-16

Signature / Date

Samples received by:

Nick Delinquent

Signature / Date

9-28-16

0925

Adelaide Environmental
1511 Rt 22, Suite C24
Brewster, NY 10509
adelaide@adelaide.com

Field Chain-of-Custody Record

Lead in Drinking Water

Turn around time: Standard
Adelaide Project # BOCE:16250.05-WA

Site:
Pearl River High School
275 East Central Avenue
Pearl River, NY 10965

District: Pearl River

Lab Project Number:

Date: 9-24-16

Inspector: Robert Se

Sample ID	Floor #	Sample Description	Analysis	Matrix	Container
16-117-PR-PRHS- CF (C) - 083	2	Room 224 Lab Sink C	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (D) - 084		D	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (E) - 085		E	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (F) - 086		F	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (G) - 087		G	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (H) - 088		H	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (I) - 089		I	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (J) - 090		J	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (K) - 091		K	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (L) - 092		L	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (M) - 093		M Teachers Table	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- CF (N) - 094		N Back Wall	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- OT - 095		Girls Locker Room Ice Machine	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- OT - 096		Boys Locker Room Ice Machine	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- OT - 097		Training Room Ice Machine	Lead	Drinking Water	250 ml Bottle
16-117-PR-PRHS- - 098			Lead	Drinking Water	250 ml Bottle

Samples taken by:

Robert Se 9-24-16

Signature / Date

Samples relinquished by:

Robert Se 9-24-16

Signature / Date

Samples received by:

Robert Se 9-28-16

Signature / Date